

## FIRST RE-ESTABLISHMENT

GCDB 340100

Quarter corner on township line Section 33, Township 34 South, Range 1 West, also Section 4, Township 35 South, Range 1 West.

Found original BT A 20" White Oak intact; also dead tree with no scribes visible to SE.

From which:

- Set a 1"x 36" galvanized pipe for corner, 36" in ground.

From which:

- The original BT bears N.57°30' W., 52.8 feet.
- Scribed a 20" white oak C.S.-BT which bears S.76°30'E., 149.5 feet.

March 17, 1931  
Boyden, Deputy County Surveyor  
Tice & Pettegrew, Chainmen

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 340100

One-quarter corner common to Section 33, Twp. 34 South, Range 1 West, and Section 4, Twp. 35 South, Range 1 West, W.M.

Found, 16 ins. below the surface of the road, the 1 ins. iron pipe set on first re-establishment (page 1) in 1931.

An original bearing tree recorded by Ives and Hyde in 1854 and noted on 1931 re-establishment:

- A white oak, now 23 ins. diam. with partly exposed lower face brs. (basis of bearing) N57°30'W to center, 53.46 feet to nail in North side of tree 4.8 feet above the ground.

A found ½ ins. diam. black iron pipe, projecting 10 ins. brs. S89°25'25"E, 29.95 feet.

I set 5/8 ins. diam. re-steel rods flush with the ground, with yellow plastic caps, marked: "JACKSON C.S." on North-South fence lines, as follows:

- 28 ins. long, brs. N43°50'40"E, 39.09 feet.
- 24 ins. long, brs. N57°30'W, 34.11 feet.

Corner lies 3 feet East of center of road.

### IN MON CASE 5/2/79

February 21, 1979

B. Malotte

R. Frost

Approved by: Edward McGinty  
County Surveyor