

**GCDB 340200**

Quarter corner to Sections 28 and 33, Township 34 South, Range 1 West.

Found the corner stake set for corner on registered Survey No. 987 in 1956 which was set midway between the first section corner East and West.

Dug a pit 2½ feet deep and 1½ feet in diameter and set a 1"x 36" galvanized iron pipe 6" in the hard pan and filled the pit with cobble stones. The top of the pipe is 10" below the surface of the present ground.

From said corner pipe, set a ¾" x 26" iron bolt on the section line to the West at 1301.2 feet, which pin falls near the top of a high bank that slopes to the West.

Continue West on said line for 24.3 feet to a shotgun barrel set for the West 1/16 Section corner.

April 11, 1957  
C. Z. Boyden  
C. L. Birk

**SEE NEXT PAGE FOR CORRECTED LOCATION**

## CORNER CORRECTION

GCDB 340200

Corrected location for the Quarter corner to Sections 28 and 33, Township 34 South, Range 1 West.

While surveying a portion of the Lila Rogers property (see Recorded Survey No. 987), a hub was set on the intersection of the North-South centerline of Section 28 with the random line as run near the South boundary of said Section.

From this random hub intersection, another hub was set North 6.92 feet for the calculated proportional  $\frac{1}{4}$  corner on the South boundary of said Section. Unfortunately, due to extensive land leveling in this area, the wrong hub was "saved" and later the wrong hub was monumented and recorded in the re-establishment records (See Re-establishment dated April 11, 1957).

A field check verified this assumption, showing the corner pipe to be 6.92 feet South of a line between the iron bolt witness corner near the West one-sixteenth section corner between Sections 28 and 33 and the iron pin at the Southeast corner of Section 28.

Therefore, I set on the iron pipe as previously set for corner and ran northerly along the North and South centerline of Section 28, 6.92 feet where I set a  $\frac{7}{8}$ " square x 22" iron pin flush with the ground surface for true corner

From which:

- The 1" galvanized iron pipe as previously set for corner (See the re-establishment dated 4/11/57) bears South  $0^{\circ}01'20''$  East, 6.92 feet;
- A  $\frac{3}{4}$ " iron bolt bears North  $89^{\circ}53'$  West along the Section line 1301.2 feet.

June 6, 1959  
M. E. Boyden  
C. L. Birk