

FIRST RE-ESTABLISHMENT

GCDB 340600

Quarter corner common to Sections 4 and 9, Township 34 South, Range 1 West.

- Found original bearing tree to the Northwest, the inside of tree is badly decayed and has been on fire. Found legible "BT" scribe.
- At record bearing and distance to the Southeast bearing tree, found pieces of burned oak and stump hole.

Set a 1"x 36" galvanized iron pipe 28" in the ground with a 2½" bronze cap stamped:

T34S, R1W
4
¼S — COR
9
C.S.
1966

From which:

- The original bearing tree (now an 18" Black Oak) bears North 23° West, 15.8 feet to the face of the lower blaze;

From said pipe corner, I establish new witness trees as follows:

- An 18" Black Oak scribed "CS-BT" bears North 34½° East, 25.2 feet to the face of the upper blaze;
- An 8" Pine scribed "CS-BT" bears North 75° West, 7.8 feet to the face of the lower blaze.

October 12, 1966
F. Roberts
G. Nygren

Approved By:
Mark E. Boyden
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 340600

One quarter corner common to Sections 4 and 9, Township 34 South, Range 1 West, W.M.

Found projecting 8 ins., the 1 ins. pipe set on First Re-establishment, with brass cap marked:

T34S R1W
4
¼S — Cor.
9
C.S.
1966

The single remaining bearing tree marked by Ives and Hyde in 1854

- A Black Oak snag with badly decayed interior, bears record N23°W, 15.84 feet to estimated face; 16.4 feet to center near base.

Trees marked on First Re-establishment measured to center of tree at lower blaze:

- Black Oak, 21-inch diameter with double healed blaze, bears N33½°E, 26.1 feet. (Record: N34½°E, 25.2 feet.)
- Ponderosa Pine, 11-inch diameter with double healed blaze, bears N75°W, 8.1 feet (Record: 7.8 feet.).

Corner lies on rocky 25% southeast slope, 10 feet North of partially down East-West fence line.

January 9, 1987
R. Romio
D. Edwards

Edward McGinty
County Surveyor

V = 19°
P.-29