

FIRST RE-ESTABLISHMENT

GCDB 400100

Corner on Township line common to Sections 33 and 34, Township 34 South, Range 1 West and Sections 3 and 4, Township 35 South, Range 1 West.

For corner, set a 1"x 36" galvanized iron pipe 36" in the ground with a 2½ ins. bronze cap stamped:

T34S & 35S, R1W	
33	34
Sec	cor.
4	3
C.S.	
1966	

From which:

- The original bearing tree, a white oak now 14" in diameter scribed "BT" bears North 52° West, 15.8 feet;
- The original bearing tree, a white oak now 12" in diameter, rotted center, bears North 48° East, 23.1 feet;
- The Southwest bearing tree has been recently blown down but the stump hole checks the record.

Marked the following new trees:

- Scribed a 14" white oak "CS-BT", which bears North 29° West 26.4 feet;
- Scribed a 10" white oak "CS-BT", which bears South 30° West 53.4 feet;
- Scribed a 6" white oak, "CS-BT", which bears North 44° East 39.2 feet.

December 27, 1966

Gary Kaiser

Gerald Nygren

Approved by:

L. D. Pinkham

Deputy County Surveyor