

## FIRST RE-ESTABLISHMENT

GCDB 400140

Quarter corner to Sections 33 and 34, Township 34 South, Range 1 West.

Found original BT to Southeast blazed but no scribe visible.

Stump hole for BT to Northwest found also and stump of line tree 25.08 feet north.

From which: Set a 1"x 36" galvanized pipe, 34" in the ground on North and South fence line and 3.5 feet south of East and West fence line;

- Scribe a 14" white oak C.S.-BT which bears S.58°E., 96.2 feet.
- Scribed a white oak C.S.-BT which bears N.74<sup>3</sup>/<sub>4</sub>°W., 113.2 feet.

May 2, 1934  
C. Z. Boyden,  
Deputy County Surveyor

L. Smith, Chainman  
G. Smith, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 400140

Quarter corner common to Sections 33 and 34, Township 34 South, Range 1 West, W.M.

Found 1-inch diameter iron pipe projecting 2 ins., set on First Re-establishment on page 5 in 1934.  
In top of said pipe set a 2½-inch diameter brass cap marked:

T34S R1W  
¼S  
33 | 34  
C.S.  
1989

No remaining evidence of original bearing trees or trees marked on First Re-establishment.

Marked new trees "CS" "BT" and take measurements to the center of tree at lower blaze:

- White Oak, 7-inch diameter, bears S57½°W, 52.78 feet.
- White Oak, 18-inch diameter, bears N35¼°W, 91.0 feet.

Both trees taken to the West because no available trees in the East.

- **Note:** 1-inch diameter iron pipe projecting 1 foot bears N3¼°W, 101.85 feet Pipe has threaded fitting on top.

Corner lies S46°E, 2.5 feet from intersection of East, West and South fence lines in broken down condition.

January 26, 1989  
T. Newcomb, Tech.  
H. Durkee, Tech.

Verlyn Thomas  
County Surveyor

V = 18°

P.-41