

**FIRST RE-ESTABLISHMENT**

**GCDB 400200**

Corner to Sections 27, 28, 33, and 34. Township 34 South, Range 1 West.

Found original bearing tree in Section 27, intact and shell of bearing tree in Section 34; also stump in Section 33.

Set corner according to the call and drove iron bar 1"x 36" for corner.

June 11, 1917.  
A. T. Brown,  
County Surveyor

Ed Dutton, Chainman  
C. Matthews, Chainman

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

GCDB 400200

Corner to Sections 27, 28, 33, 34, Township 34 South, Range 1 West.

Found original BT now a 30" White Oak with BT.

Scribe intact, no other definite evidence of BTs. From said scribed BT on the record course and distance set a 1"x 31" sharpened iron pin flush with the pavement on the Crater Lake Highway for corner.

From which:

- An 8" White Oak scribed CS-BT bears South  $39\frac{1}{2}^{\circ}$  East, 56.5 feet;
- Scribe an 8" White Oak CS-BT which bears North  $83^{\circ}$  East, 42.1 feet;
- An electric Transmission Pole No. A607 bears North  $24\frac{3}{4}^{\circ}$  West, 86.0 feet set a 1"x19" iron pin which bears West, 30.0 feet.

November 6, 1952  
C. Z. Boyden  
C.L. Birk

**SEE:** RPs to Corners in Danger of Construction book, page 6.

R. Frost 2/9/83


**SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT**

**THIRD RE-ESTABLISHMENT**

**GCDB 400200**

Section corner common to Sections 27, 28, 33 and 34, Township 34 South, Range 1 West, W.M.

From the following evidence at the location described below, set a 1x30-inch diameter flanged galvanized iron pipe, set 24 ins. in the ground in concrete, with a 2½-inch diameter attached brass cap marked:



Ref. Mon.  
1994  
Jackson County Surveyor

True section corner location bears N68°E, 70.45 feet. See RP book of Corners in Danger of Construction, page 13, dated 1983.

References set in 1983, ¾-inch diameter rebars found:

- Bears S68°W, 287.02 feet flush at the east edge of curbing and halfway between the ends north and south to breeze-way of the United Methodist Church.
- Bears S68°W, 162.55 feet 3 ins. deep.
- Bears S68°W, 30.45 feet 3 ins. deep.

New references taken:

Gray brick entrance gate to residence (no number), east side of Highway 62:

- Northwest corner bears N81°37'50"E, 196.92 feet.
- Southwest corner bears S86°55'20"E, 189.85 feet.

Corner lies on west side of Highway No. 62. Set a 5½ feet steel fence post with attached location tag along side of corner.

July 12, 1994  
T. Newcomb, Tech.  
J. Burgess, Tech.

Verlyn Thomas  
County Surveyor

P.-118

**SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT**

**FOURTH RE-ESTABLISHMENT  
GCDB 400200**

Reference monument common to Sections 27, 28, 33, and 34 of Township 34 South, Range 1 West, W.M.

Found at reference monument position , monument knocked out of ground. From the following evidence, re-set 1 x 30 ins. diam. flanged galv. Iron pipe with 2 ½ ins. diam brass cap flush in concrete and marked:

Jackson County Surveyor  
T34S R1W  
S28 | S27  
—+—  
S33 | S34  
Ref Mon  
2009

Steel post 2 ft. west

Found references recorded on Second Re-establishment in 1952, ¾ x 24 ins. rebars and re-measured

- Brs. record S68°W, 287.02 ft. flush at the east edge of curbing and halfway between the north and south ends of breeze-way of the United Methodist Church.
- Brs. record S68°W, 162.55 ft. 3 ins. deep.
- Brs. record S68°W, 30.45 ft. 3 ins. deep.

Found references recorded on third re-establishment in 1994 and re-measured;  
The top north-west and south-west corners of concrete block gate;

- Brs. N81°35'44"E, 196.87 ft.; record N81°37'50"E, 196.92 ft.
- Brs. S86°50'54"E, 189.70 ft.; record S86°55'20"E, 189.85 ft.

True corner lies N68°E, 70.45 ft. near center of Crater Lake Hwy

March 11, 2009

B. Beeman  
H. Durkee

Kerry K. Bradshaw  
Jackson County Surveyor

P. – 46

V – Nikon Total  
Station