

FIRST RE-ESTABLISHMENT

GCDB 400300

Corner Sections 21, 22, 27, and 28, Township 34 South, Range 1 West, Willamette Meridian.

Found

- Original BT to Southeast with scribe marks visible.
- Also remains of the stump of the original BT to Southwest both BTs were identified by Joseph J. Hall, an old resident.

From which evidence"

- Set a 2"x 40" galvanized iron pipe for corner, from which a 14" Black Oak scribed CS-BT which bears North 43° East 38.52 feet.
- Scribe a 11" White Oak CS-BT which bears South 15° East, 79.82 feet.
- Scribed a 12" Black Oak which bears South 9° West 167.5 feet, the center of Crater Lake Highway bears West 231.5 feet.

October 22, 1945
C. Z. Boyden
R. E. Welch
F. Foley

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 400300

Section common to Sections 21, 22, 27, and 28, Twp. 34 South, Range 1 West, W.M.

Found, 6 ins. below the surface of the ground, the 2-inch diameter iron pipe set on First Re-establishment, page 8, in 1945.

Inside found pipe I set a 1x36-inch G.I. pipe, (6 ins. deep) with 2½-inch diameter bronze disc marked:

JACKSON COUNTY 1979
T34S R1W
21 | 22
—+—
28 | 27
C.S.

Bearing trees marked on First Re-establishment found as follows:

- Sawed Black Oak stump, 18-inch diameter, bears N43°E, 39.56 feet to center. Record: N43°E, 38.52 feet.
- White Oak, 20-inch diameter, scribed "C" in partially opened upper face, bears S15°E, 80.12 feet to scribed face. Re-measured 80.25 feet to center. Record: S15°E, 79.82 feet

I set a 5/8 x 30 ins. re-steel rod, 1 ins. below the surface of the ground with yellow plastic cap marked "JACKSON C.S." which bears S89°21'E, 25.20 feet.

An 8d nail in the Northwest side of Power Pole No. A4006, bears S22°38'W, 9.27 feet.

The most Northwest corner of the concrete footing of wood frame building, bears S63°57'W, 46.52 feet.

Corner lies 196.5 feet East of Crater Lake Highway.

April 6, 1979
J. Swanson
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 400300

Section corner common to Sections 21, 22, 27 and 28, Township 34 South, Range 1 West, W.M.

Found 6 ins. deep, 8 ins. Southeast of the wood post corner (with attached location marker) of North and West bearing hog wire fence lines, the 1-inch diameter pipe set on First Re-establishment, dated 1979.

The pipe is found disturbed and bent, with brass cap missing. Remove this pipe along with the 2-inch diameter pipe set on First Re-establishment in 1945 and replace same with a 1x36-inch Galvanized iron pipe, set flush, with a 2½-inch diameter brass cap marked:

T34S R1W	
21	22
28	27
C.S.	
1989	

Note: The disturbed monuments were reportedly removed by "the power company" and reset near their original location.

- Mound stones around corner and re-measure references recorded on Second Re-establishment.
- At record location of Oak stump, found stump hole with stump (dislodged) lying nearby.

The remaining references, described below, are found at (1979) record bearing(s) and distance(s):

- White Oak, now 22-inch diameter, with healed blazes bears S15°E, 80.25 feet to center of the tree near base.
- A 5/8-inch diameter rebar, found 2 ins. deep, with yellow plastic cap marked "Jackson C.S.", bears S89°21'E, 25.20 feet.
- A nail in the Northwest face of Power Pole No.A4006, bears S22°38'W, 9.27 feet.
- The Northwest corner of concrete footing of wood frame building, bears S63°57'W, 46.52 feet.

Set a new reference; 5/8 x 24 ins. rebar, flush, with yellow plastic cap marked "Jackson C.S.", bears S1°16'E, 14.93 feet.

Corner lies about 196 feet East of Crater Lake Highway and near the West edge of dirt road c. North-South.

May 31, 1989
R. Frost, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

P.-134