

FIRST RE-ESTABLISHMENT

GCDB 400440

Quarter corner, Sections 15 and 16, Township 34 South, Range 1 West.

- Found original Yellow Pine witness tree in Section 16.
- Other tree destroyed.

Set post and blazed a BP 16" in diameter which bears N.37½°E., 61.15 feet.

June 19, 1913
A. T. Brown,
Deputy County Surveyor

C. D. Runyon, Chainman
M. B. Kellogg, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 400440

Quarter corner to Sections 15 and 16, Township 34 South, Range 1 West.

Found stake to marked corner; also stump holes to correspond with original BTs; also Pine BT lying on ground, marked as described by County Surveyor Brown as re-established by him in 1913;

From which evidence:

- Set a 1"x 36" galvanized pipe 30" in the ground for corner.

From which:

- A 5" Black Oak scribed CS-BT bears North $51\frac{3}{4}^{\circ}$ West 23.35 feet.
- Scribe a 5" White Oak CS-BT which bears $S19\frac{1}{2}^{\circ}E$ 20.2 feet.

June 7, 1935
C. Z. Boyden,
Deputy County Surveyor

O. H. Tice, Chainman

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 400440

One-Quarter corner common to Sections 15 and 16, Twp. 34 South, Range 1 West, W.M.
 $V = 19\frac{1}{2}^\circ$

Found, projecting 1 ins. in a mound of stone, the 1-inch diameter, G.I. pipe, set on Second Re-establishment, page 7, in 1935.

I replaced found pipe with, and deposited it along a 1x36-inch G.I. pipe set 35 ins. in the ground with a $2\frac{1}{2}$ ins. bronze disc marked:

JACKSON COUNTY 1979
T34S R1W
16 | 15
¼S

From which:

- The single remaining bearing tree, a White Oak, marked on Second Re-establishment, now 12-inch diameter, with healed blazes, bears Record: $N51\frac{3}{4}^\circ W$, 23.35 feet to estimated face. Re-measured 23.56 feet to center of tree.

Two Ponderosa Pine reference trees, double blazed by person(s) unknown, approximately 35 years ago (growth ring count) found as follows:

- 18-inch diameter bears $N71^\circ E$, 45.50 feet to center of tree at lower blaze. I scribe this tree "CS" "BT".
- 9-inch diameter, with opened upper blaze, bears $N48^\circ W$, 20.54 feet to center of tree.

April 4, 1979
J. Swanson
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 400440

Quarter corner common to Sections 15 and 16, Township 34 South, Range 1 West, W.M.

Found lying on the ground, the pipe and brass cap described on Third Re-establishment, dated 1979. This corner monument was apparently removed by bulldozer in clearing and/or road construction.

From evidence of extant bearing trees, set a 1x36-inch Galvanized iron pipe, 6 ins. deep, with a 2½-inch diameter brass cap marked:

T34S R1W
¼S
16 | 15
C.S.
1988

From which:

- A bearing tree marked on Second Re-establishment, dated 1935 and reported in 1979 (as White Oak),
- A Black Oak, now 14-inch diameter, with healed blazes, bears Record: N51°45'W, 23.35 feet to estimated face, 23.56 feet to center of tree at lower blaze.

Bearing trees reported found in 1979 (origin unknown):

- Ponderosa Pine, 17-inch diameter containing scribed "CS" & "BT" in partly healed faces, bears Record: N71°E, 45.5 feet to center of tree at lower blaze.
- Ponderosa Pine, 10-inch diameter with exposed upper face (no scribe) bears Record: N48°W, 20.54 feet to center of tree at base.

Corner lies near middle of newly constructed (dirt) private road c. East and about 5 feet South of metal fence post with attached location marker.

September 28, 1988
R. Frost, Tech.
S. Beecher, Tech.

Edward McGinty
County Surveyor

P.-349