

FIRST RE-ESTABLISHMENT

GCDB 440400

Quarter corner to Sections 15-22, Township 34 South, Range 1 West.

Found original BT to Northwest plainly scribed; also remains of BT to Southeast

From which:

Set a 1"x 36" galvanized pipe for corner which checks mound of stone found at corner.

- Scribed a 24" White Oak C.S.-BT which bears S45°15'W, 100.9 feet.
- Scribed a 10" White Oak C.S.-BT which bears N75°30'E, 246.3 feet.

June 29, 1931
Boyden, Deputy County Surveyor
Pettegrew, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 440400

Quarter corner common to Sections 15 and 22, Township 34 South, Range 1 West, W.M.
 $V = 18\frac{1}{2}^\circ$

Found the 1 ins. pipe set in 1931 in a North-South fence line along the Easterly edge of a driveway.

From which:

- The 10 ins. White Oak as marked in 1931 bears Record: $N75\frac{1}{2}^\circ E$ 246.3 feet (246.8 feet to center). This tree is in good condition and was not opened. N.W. tree has been removed.

Marked a new tree C.S. BT and measured to center of tree at the lower blaze:

- A White Oak, 10½-inch diameter, bears $N42\frac{1}{2}^\circ W$, 66.1 feet (falls in barnyard).

July 2, 1974
E. Graham
K. Weaver

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 440400

Quarter corner common to Sections 15 and 22, Township 34 South, Range 1 West, W.M.

Found projecting 1 in. the 1 in. diam. iron pipe, set on First Re-establishment in 1931. In the top of said pipe, set a 2½-inch diameter brass cap marked:

T34S R1W
15
¼S —
22
CS
1989

Bearing tree marked on first and reported on Second Re-establishment in 1974 is now gone.
Bearing tree falls in cleared field.

Bearing tree marked on Second Re-establishment found:

- White Oak, 13-inch diameter, with healed blazes bears N42½°W 66.30 feet to center of tree at lower blaze. Record distance 66.10 feet.

Marked new tree "CS" "BT":

- White Oak 13-inch diameter bears S73¾°W, 82.37 feet to center of tree at lower blaze.

Corner lies ½ feet west of wooden fence post with fence line running north and south. Dirt driveway bears West 11 feet.

September 10, 1989
T. Newcomb, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

V = 19°
P.-203

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 440400

Quarter corner common to Sections 15 and 22, Township 34 South, Range 1 West, W.M.

Corner monument recorded on Third Re-establishment in 1989, not found, presumably destroyed by gate and fence construction.

Using co-ordinate ties supplied by Kaiser Surveying, set at the corner position, a 1x30-inch Galvanized iron pipe with a 2½-inch diameter brass cap, exposed 2 inches and marked:

JACKSON COUNTY SURVEYOR
T34S R1W
S15
¼S —
S22
2005

Bearing trees recorded on said Third Re-establishment found and measured to center of tree at lower blaze:

- White Oak, now 14-inch diameter with healed double blazes bears N42½°W, 66.8 feet. Record: 66.30 feet.
- View of southwesterly tree now obstructed by new gate. (White Oak, now 14-inch diameter with healed double blazes)

Take new references, northeasterly corners of 10x10 ins. I-beam gate posts, bears:

- N85°24'05" 21.97 feet (westerly post)
- S72°08'55"W, 5.45 feet (easterly post)

Corner lies approximately 10 feet easterly of gravel driveway and approximately 1 foot westerly of barbed-wire fence.

May 3, 2005

H. Durkee

T. Newcomb

Roger R. Roberts

Jackson County Surveyor

P. - 47

SEE NEXT PAGE FOR FIFTH RE-ESTABLISHMENT

**FIFTH RE-ESTABLISHMENT
GCDB 440400**

Quarter corner common to Sections 15 and 22 of Township 34 South, Range 1 West, W.M.

Corner monument erroneously set on 4th re-establishment, a 1 x 30 ins. galv. iron pipe with a 2½ ins. diam. brass cap, removed and re-set flush, in a ring of stones, at true corner position being N69°56'53"W, 0.80 ft. from old position, and marked;

T34SR1W
S15
—— ¼
S22
2005

Bearing trees recorded on 3rd re-establishment found with healed double blazes and measured to center at lower blaze;

- W. oak now 15 ins. diam. brs. N41°37'00"W, 66.2 ft. record; N42½°W, 66.3 ft.
- W. oak now 15 ins. diam. brs. southwesterly, view obstructed by new gate.

References recorded on 4th re-establishment found and measured to northeast corners of 10 x 10 ins. I-beam gate posts;

- Easterly post brs. S68°00'03"W, 4.86 ft.
- Westerly post brs. N85°02'12"W, 21.60 ft.

Corner lies approx. 10 ft. east of driveway and approx. 1.5 ft. west of barbed-wire fence.

April 7, 2010

B. Beeman
H. Durkee

Kerry K. Bradshaw
Jackson County Surveyor

P – 75
V – Nikon Total Station