

FIRST RE-ESTABLISHMENT

GCDB 600100

Section corner common to Section 35 and 36, Twp. 34 South, Range 1 West, and Section 1 and 2, Twp. 35 South, Range 1 West, W.M. $V = 18^\circ$

From the following evidence, at the location described below, I set a 1x36-inch G.I. pipe, 30 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1978	
T34S	R1W
35	36

2	1
T35S	

Original bearing trees recorded by Ives and Hyde in 1854, found as follows:

- White Oak, 16 ins. diam., containing reverse impression of scribe marks, including "T34S S36" brs. Record: $N65^\circ E$, 23.76 feet to scribed face.
- The stump remains of a down laurel, 16 ins. diam., containing reverse impression of scribe marks in upper and "BT" in lower face brs. record: $N42^\circ W$, 20.46 feet on slope.

I mark new trees CS BT and take measurements to center of trees at lower blaze.

- White oak, 11 ins. diam., brs. $S55^\circ E$, 31.59 feet.
- Cedar, 11 ins. diam., brs. $S12^\circ E$, 74.82 feet
- Black oak, 6 ins. diam., brs. $S18\frac{3}{4}^\circ W$, 44.27 feet.
- Laurel, 6 ins. diam., brs. $N38^\circ W$, 17.48 feet.

Note: No suitable tree in NE quadrant.

Corner lies on SE slope, about 165 feet $N30^\circ E$, from corner of N and E-W bearing fence lines.

January 31, 1978

B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor