

FIRST RE-ESTABLISHMENT

GCDB 600340

Quarter corner to Sections 23 and 24, Township 34 South, Range 1 West, W.M.

- Found original BT to Southwest, plainly scribed, (BT in poor condition).
- Also found BT to Northeast lying on the ground;

From which evidence, set a 1"x 36" galvanized pipe 26" in the ground for corner.

From which:

- A 16" Black Oak scribed C.S.-BT bears $N60\frac{3}{4}^{\circ}W$, 38.0 feet.
- Scribe a 12" White Oak C.S.-BT which bears $S30\frac{1}{4}^{\circ}E$ 47.5 feet.

June 7, 1935
C. Z. Boyden,
Deputy County Surveyor
O. H. Tice, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600340

One-Quarter corner common to Sections 23 and 24, Township 34 South, Range 1 West, W.M.

Found, 6 ins. West of wood post corner of North and East bearing fence lines, the 1x36-inch G.I. pipe projecting 10 ins., set on First re-establishment, page 6, in 1935.

I replace the above with and deposit it alongside a 1x36-inch G.I. pipe set 28 ins. in the ground with a 2½ ins. bronze disc marked:

JACKSON COUNTY 1980
23 | 24
¼S

Bearing trees marked on First Re-establishment found as follows:

- White Oak, 15-inch diameter, with axed into upper face, bears Record: S30°15'E, 47.50 feet to estimated face. Re-measured 48.00 feet to center of tree at lower blaze.
- Black Oak, 16-inch diameter with healed blazes, bears N60°25'W, 38.67 feet to center of tree at lower blaze. Record: N60¾°W, 38.0 feet.
- An original bearing tree marked by Ives and Hyde in 1854, a Black Oak, now 14-inch diameter with rotted interior, bears Record: S87°W, 25.08 feet to estimated face. Re-measured; 25.41 feet to center of tree at upper blaze.

I mound stones around corner and mark a new tree "CS" "BT":

- White Oak, 6-inch diameter bears S58°30'E, 38.40 feet to center of tree at lower blaze.

Corner lies about 125 feet West of road at cattle guard.

May 22, 1980

R. Frost

D. Danielsen

Approved by: Edward McGinty
County Surveyor