

FIRST RE-ESTABLISHMENT

GCDB 600700

Section corner common to Section 35 and 36, Twp. 33 South, Range 1 West, and Section 1 and 2, Twp. 34 South, Range 1 West, W.M. $V = 19\frac{1}{2}^\circ$

Found projecting 2 ins., the $\frac{5}{8}$ inch diam. re-steel rod, set in 1968, by L. Ager on Survey No. 3662.

Original BTs recorded by Ives and Hyde in 1854, found as follows:

- The stump hole of a down and rotted Pine, now about 18-inch diameter, found at record location of N.E. BT.
- Burned Pine stump remains found at record location of S.E. BT.
- Stump hole of a down, decayed Pine containing old axe work found at record location of N.W. BT.
- Black Oak, about 22-inch diameter, with center rotted out, bears Record: $S58^\circ W$, 23.1 feet to estimated lower face.

Over found rod, I set a 1x36-inch G.I. pipe 30 ins. in the ground with a $2\frac{1}{2}$ ins. bronze disc marked:

T33S	R1W
35	36
2	
	1
T34S	

Jackson County 1976

I marked new trees C.S. BT and take measurements to center of trees at lower blaze:

- Douglas Fir, 12-inch diameter, bears $N76\frac{1}{2}^\circ E$, 26.50 feet.
- Douglas Fir, 9-inch diameter, bears $S31^\circ E$, 15.37 feet (This is recorded witness tree on Survey No. 3662.)
- Ponderosa Pine, 8-inch diameter, bears $S14^\circ W$, 23.50 feet.
- Douglas Fir, 10-inch diameter, bears $N24\frac{1}{2}^\circ W$, 37.82 feet.

Corner lies on West slope, about 50 feet south of draw and about 450 feet East of location marker on 16-inch diameter Maple alongside road.

July 7, 1976

B. Malotte

R. Frost

Approved by: Edward McGinty

County Surveyor