

FIRST RE-ESTABLISHMENT

GCDB 640100

Quarter corner to Section 36, Township 34 South, Range 1 West, and Section 1, Township 35 South, Range 1 West, W.M. $V = 17^\circ$

From the following evidence, at the location described below, I set a 1x36-inch G.I. pipe, 30 ins. in the ground with a $2\frac{1}{2}$ ins. bronze disc marked:

Jackson County 1978
T34S R1W
36
 $\frac{1}{4}$ S —
1
T35S

Original bearing trees recorded by Ives and Hyde in 1854 found as follows:

- The base and stump depression of a down and rotted black oak, approximately 10 ins. diam., (located on E-W fence line) containing evidence of old axe work, brs. $S62^\circ E$, 62.04 feet. Record: $S62^\circ E$, 48.84 feet.
- **Note:** Probable transposition of 94 links to (recorded) 74 links.
- The base and stump hole of a down and rotted pine, 10 ins. diam., scribed " $\frac{1}{4}$ S" in exposed face brs. Record: $N7^\circ W$, 10.56 feet.

I mound stones around corner, mark the following trees CS BT and take measurements to center of trees at lower blaze:

- White oak, 5 ins. diam., brs. $N78\frac{3}{4}^\circ E$, 75.32 feet.
- White oak, 4 ins. diam., brs. $S38^\circ W$, 38.18 feet.

Corner lies on East slope, approximately 65 feet and 200 feet East of spring branches, c SSE and 38 feet North of E-W fence line.

January 31, 1978

B. Malotte

R. Frost

Approved by: Edward McGinty
County Surveyor