

FIRST RE-ESTABLISHMENT

GCDB 640700

Quarter corner common to Section 36, Township 33 South, Range 1 West and Section 1, Township 34 South, Range 1 West, W.M.

Found the $\frac{3}{4}$ " x 24" iron pipe set for corner by Surveyor L. E. Ager on Recorded Survey No. 2302. Replaced said pipe with a 1"x 36" galvanized iron pipe 35" in the ground with a 2½" bronze cap stamped:

T33-34S R1W
36
¼S — Cor.
1
C.S.
1971

For corner, from which:

- The original bearing tree (now a 16" Black Oak in poor condition with rotted out faces) bears N25½°W, 42.4 feet to the lower face (original Record: 14" Black Oak N25°W, 42.2 feet);
- The original bearing tree (now a 33" Laurel with "¼" scribe visible) bears S50½°E, 31.2 feet to the face of the upper blaze (original Record: 15" Laurel S38°E, 31.0 feet).
- Found the 20" Fir scribed "¼ S BT" on single blaze by Surveyor Ager which bears S40°E, 8.7 feet to the face of the blaze (Recorded Survey No. 2302: 24" Fir S40°E, 9.3 feet to the center).

Marked a new tree as follows:

- A 16" Fir scribed "CS-BT" which bears N72½°E, 3.7 feet to the face of the lower blaze.

January 5, 1971
Gary Kaiser,
Deputy County Surveyor

Lloyd Shreeve