

## FIRST RE-ESTABLISHMENT

GCDB 700200

Corner to Sections 25 and 36 in Township 34 South, Range 1 West, and Sections 30 and 31, in Township 34 South, Range 1 East, W.M.

Found the 2" galvanized iron pipe, exposed 13", set for corner by Deputy County Surveyor C. Z. Boyden on December 3, 1936 but not recorded.

Drove a 1"x 36" galvanized iron pipe inside 2" pipe, and set a 2½" brass cap stamped:

T34S, R1W-R1E  
25 | 30  
Sec. ——— | ——— Cor.  
36 | 31  
C.S.  
1972

From which:

- The original bearing tree, now a 24" burned out White Oak with scribe "BT" visible, bears S25½°W, 92.6 feet to face of the lower blaze (original Record: 15" White Oak, S25°W, 91.1 feet);
- The original bearing tree, now a 26" White Oak snag with two faces and no scribing, bears N26°W, 82.2 feet to face of the lower blaze (original Record: 20" White Oak, N26°W, 81.8 feet).

June 19, 1972  
Lloyd Shreeve  
Stephen Woodcock

Approved By:  
Gary D. Kaiser  
Deputy County Surveyor