

FIRST RE-ESTABLISHMENT

GCDB 700700

Township corner on Willamette Meridian, to Townships 33 and 34, Ranges 1 East and 1 West.

- Found remains of all four BTs which had been destroyed by fire. No scribes visible.
- BTs checked with distance and course, corner also falls on blazed line to North, East, and West.
- Could find no blazed line to South. Corner also checks with line tree to East.
- Mr. George Weeks also identifies this location as being correct as identified by him in 1909, when the scribes were visible.

Set 4" x 4" x 36" black oak stake 18" in the ground for corner.

From which:

- A 30" yellow pine scribed C.S.-BT bears N57°15'E, 24.3 feet.
- A 14" red fir scribed C.S.-BT bears N59°15'W, 31.4 feet.
- A 16" red fir scribed C.S.-BT bears S78°W, 45.0 feet.
- A 32" yellow pine scribed C.S.-BT bears S19°45'E, 51.0 feet.

June 12, 1930
Boyden,
Deputy County Surveyor

Tice, Pettegrew, W. S. Doty and George Weeks,
Chainmen

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 700700

Township corner common to Township 33 and 34 South, Range 1 West and 1 East, W.M.

Found no evidence of the Oak stake set for corner on the First Re-establishment by Deputy County Surveyor, C. Z. Boyden on June 12, 1930.

Set 1"x 36" galvanized iron pipe 36" in the ground with a 2½" bronze cap stamped:

T33-34SR1W-1E
36 | 31
TWP—|— Cor.
1 | 6
C.S.
1971

From which:

- A stump hole checks position of original bearing tree to the Southwest;
- The bearing tree established on the said First Re-establishment (now a sawed Pine stump with "BT" scribe visible) bears S19½°E, 50.9 feet to the face of the lower blaze (First Re-establishment: 32" Yellow Pine S19°45'E, 51.0 feet);
- The bearing tree established on the said First Re-establishment (now a 36" Fir in good condition with "BT" scribe visible) bears S78°W, 45.0 feet to the face of the lower blaze (First Re-establishment: 16" Fir S78°W, 45.0 feet);
- The bearing tree established on the said First Re-establishment (now a sawed Fir stump with "BT" scribe visible) bears N59¼°W, 31.3 feet to the face of the lower blaze (First Re-establishment: 14" Fir N59°15'W, 31.4 feet)
- The bearing tree to the Northeast established on said First Re-establishment has been destroyed by logging.
- Scribed a double blazed 12" Fir "CS-BT" all on lower face, which bears N60¼°W, 74.8 feet to the face of the lower blaze;
- Scribed a double blazed 14" Fir "CS-BT" all on lower face, which bears N7¾°W, 101.5 feet to the face of the lower blaze;
- Scribed a double blazed 13" Fir "CS-BT" all on lower face, which bears S47½°E, 90.2 feet to the face of the lower blaze.

January 6, 1971
Gary Kaiser, Deputy County Surveyor
Lloyd Shreeve

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 700700

Township corner common to Township 33 and 34 South, Range 1 West and 1 East, W.M.

Found at the corner, about 1-inch deep, the 1-inch diameter galvanized iron pipe with 2½-inch diameter brass cap set in the top and marked:

T33-34SR1W-1E
36 | 31
TWP—|—Cor.
1 | 6
C.S.
1971

Bearing trees marked on First Re-establishment in 1930 found:

- Douglas Fir, now 39-inch diameter with opened lower blaze (no scribing visible) bears Record: S78°W, 45.0 feet to face of lower blaze.
- Sawed Douglas Fir stump, now 27-inch diameter with visible scribe marked "BT" on lower blaze bears Record: N59¼°W, 31.4 feet to face.

Bearing trees marked on Second Re-establishment in 1971 (T34S, R1E) found:

- Douglas Fir, now 16-inch diameter with double healed blazes bears N59¾°W, 75.3 feet to center of tree at base. Record: N60¼W, 74.8 feet to face at lower blaze.
- Sawed Douglas Fir stump, now 24-inch diameter with healed lower blaze bears Record: S47½°E, 90.2 feet to face of lower blaze.

Marked new trees "CS" "BT" and took measurements to center of tree at lower blaze:

- Douglas Fir, 8-inch diameter bears N55¾°E, 11.0 feet.
- Douglas Fir, 6-inch diameter bears S25¾°E, 34.6 feet.

Corner found about 1 inch deep, in the middle of a logging road in a long curve.

March 11, 1992
H. Durkee, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V-18¾°

P. -8