

FIRST RE-ESTABLISHMENT

GCDB 100140

Quarter Section Corner on Range line Section 36, Township 34 South Range 1 East and Section 31, Township 34 South, Range 2 East

Found the snag of the NE. BT with the $\frac{1}{4}$ BT scribe legible also the stump in place with part of the scribe visible on the down snag

From which evidence

- Set a 1"x 34" galvanized iron pipe 28" in the ground for corner.

From which

- An 8" white oak scribed CS-BT bears North 28° West 75.3 feet.
- Scribe a 8" white oak CS-BT which bears North 69° East 57.1 feet.

March 2, 1953
C. Z. Boyden
Mark Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 100140

Quarter corner common to Sections 31 and 36, Township 34 South, Ranges 1 and 2 East, W.M.

Found projecting 6 ins. in large mound of stone, 3-inch diameter standard BLM brass cap marked:

T34S
¼
R1E | R2E
S36 | S31
1968

- The original northeast bearing tree marked by Ives and Hyde in 1854, now a Pine snag with BT scribe visible bears Record: N82°E.
- The stump shell of the original Northwest bearing tree, an Oak, bears Record: N32°W.

Trees marked on first county re-establishment in 1953 and measured to center of tree at lower blaze:

- White Oak, 9-inch diameter with healed blazes bears N28°W, 75.25 feet. Record: 75.3 feet.
- White Oak, 8-inch diameter with healed blazes bears N67°E, 57.45 feet. Record: N69°E, 57.1 feet.

Trees marked by the BLM in 1968: (Measured to center of tree near base).

- Fir snag, 8-inch diameter with scribing visible in partially healed blaze bears N30½°W, 20.50 feet. Record: N30°W, 20.46 feet.
- Pine, 19-inch diameter with healed blaze, bears N23½°E, 77.65 feet. Record: N24°E, 77.88 feet.

Mark a new tree "CS" "BT":

- Pine, 9-inch diameter bears N62½°W, 8.08 feet to center of tree at lower blaze.

Corner lies on a moderate South slope in Blackberry thicket approximately 350 feet South of Butte Falls Highway

January 29, 1987
R. Romio
D. Edwards

Edward McGinty
County Surveyor

V = 19°
P.-26