

FIRST RE-ESTABLISHMENT

GCDB 100640

Quarter corner common to Sections 1 and 6, Township 34 South, Range 1 & 2 East.

Found a 1½"x? iron pipe with a galvanized cap stamped:

S 6
MEDCO
S 1

From which:

- A 20" Fir with BT scribe bears South 16° East, 8.7 feet;
- A fir snag with old face badly burned, bears South 88° West, 20.5 feet to the upper face;
- The center of a 24" fir, original line tree bears South 7.1 feet.

Scribed a 7" Fir CS-BT which bears North 9.0 feet to the face of the lower blaze.

September 13, 1967
L. D. Pinkham, Deputy County Surveyor
Gary Kaiser

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 100640

Quarter corner common to Section 1, Township 34 South, Range 1 East, W.M. and Section 6, Township 34 South, Range 2 East, W.M.

Found at the corner, the 1½-inch diameter iron pipe with the galvanized "Medco" cap described on First Re-establishment, dated 1967.

Remove said cap and set inside said pipe, a 1x36-inch Galvanized iron pipe, projecting 11 ins. with 2½-inch diameter brass cap marked:

T34S
¼S
R1E 1 | 6 R2E
CS
1990

Original evidence recorded by Ives and Hyde in 1854 found:

- Fir, now a sawed stump, 28-inch diameter and one foot high, "line tree", bears South, 7.1 feet to center at base. Record: 6.6 feet.
- Fir, now a sawed stump, 21-inch diameter and 4.5 feet high, bears S16°E, 8.9 feet to center at base. Record: 8.6 feet to face.

Bearing tree marked on First Re-establishment found:

- Douglas Fir, now 16-inch diameter, with healed blazes, bears North, 9.2 feet to center of tree at lower blaze. Record: 9.0 feet.

Mark new trees "CS" "BT" and take measurements to center of tree at lower blaze:

- Douglas Fir, 8-inch diameter, bears S74½°E, 45.85 feet.
- Cedar, 6-inch diameter, bears N48½°W, 10.45 feet.
- Cedar, 6-inch diameter, bears S32°W, 7.5 feet.

Corner lies on Westerly slope, approximately 200 feet West of graveled road.

November 14, 1990
H. Durkee, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 18½°
P.-142