

## FIRST RE-ESTABLISHMENT

### GCDB 100700

Section corner common to Section 36, Township 33 South, Range 1 East, Section 31, Township 33 South, Range 2 East, Section 1, Township 34 South, Range 1 East and Section 6, Township 34 South, Range 2 East, W.M.

Found the 2-inch diameter iron pipe with welded on brass cap marked:

36	31
1	6
RS461	

Protruding 9 ins. above the ground as set on Survey No. 2482 dated 1964.

We add marks to cap which now appears as:

T33S	
R1E	R2E
36	31
1	6
T34S	
CS 1988	
RS461	

And take measurements to the bearing trees marked on the above noted survey.

Trees measured to center at lower blaze:

- White Fir, 19-inch diameter, with healed double blazes, bears Record: N40°E, 29.65 feet. Record distance; 29.5 feet.
- Douglas Fir, 10-inch diameter, with healed double blazes, bears Record: S76°E, 8.0 feet. Record distance 7.4 feet.
- Douglas Fir, 11-inch diameter, with healed double blazes, bears N41½°W, 14.55 feet. Record: N44°W, 14.3 feet.
- The Southwest bearing tree has been cut down and no other tree was available for marking in the clear-cut.

Corner lies at corner of timber and N14°E, 520 feet of road ending in clear-cut.

November 23, 1988  
S. Beecher, Tech.  
T. Newcomb, Tech.

Edward McGinty  
County Surveyor

V = 18½°

P. -381