

FIRST RE-ESTABLISHMENT

GCDB 240200

Quarter Section Corner 29 - 32, Township 34 South, Range 2 East.

Found the original Southeast BT now a 30" fir with the $\frac{1}{4}$ S Scribe exposed. No evidence of the other BT from the said 30" fir by official record

- Set a 1" x 36" galvanized iron pipe 30" in the ground for corner

From which:

- The original BT, a 30" fir bears South 45° East, 21.12 feet;
- Scribe a 30" cedar scribed CS-BT bears North 39°East 51.7 feet (to the upper scribe)

October 29, 1954
C. Z. Boyden
Tom Furnas
M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 240200

Quarter corner common to Sections 29 and 32, Township 34 South, Range 2 East, W.M.

Found projecting 2 ins., the 1-inch diameter galvanized iron pipe set on First Re-establishment, page 4, in 1954.

The single remaining original bearing tree marked by Nathaniel Ford in 1855 found:

- Fir stump, 44-inch diameter with scribe marks including "¼S" visible, bears Record: S45°E, 21.01 feet to face. Record distance 21.12 feet.

Bearing tree marked on said First Re-establishment found:

- Cedar stump, 30-inch diameter, bears S86½°W, 82.2 feet to center. Record: S86¼°W, 81.2 feet to face.

Scribe new trees "CS" "BT" and measure to center of trees at lower blaze:

- Douglas Fir, 10-inch diameter, bears S34°W, 6.55 feet.
- Douglas Fir, 5-inch diameter, bears N13°W, 16.12 feet.

Corner lies 30 feet South of a dirt road, course S70°E, and an estimated 150 feet North of an irrigation canal.

May 1, 1987
D. Edwards - Tech II
S. Beecher - Tech I

Edward McGinty
County Surveyor

V = 18½°
P.-139

NOTE: 11/29/89
Stamped on Brass Cap:

T34S R2E
29
¼S —
32
CS
1989

S. Beecher
T. Newcomb