

FIRST RE-ESTABLISHMENT

GCDB 240600

Quarter corner common to Sections 5 and 8 of Township 34 South, Range 2 East, W.M.

Found at corner position exposed 6 ins. in mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1968 and marked:

T34S R2E
S5
¼—
S8
1968

Single remaining original bearing tree recorded by Nathaniel Ford of the GLO in 1855 found and measured to center at base;

- W. fir sawed stump brs. S45°W, 9.0 ft.; record 8.6 ft.

Bearing trees recorded by the BLM in 1968 found with healed single blazes and measured to center at base:

- Fir sawed stump brs. N21½°E, 58.1 ft. ; record N23°E
- Fir rotted stump brs. record S61°W, 74.6 ft.

Bearing trees recorded on Survey #13463 by Arthur R. Rambo in 1993 found with healed double blazes and measured to center at lower blaze;

- D. fir now 15 ins. diam. brs. N42½°W, 8.0 ft.; record N43°34'W, 8.4 ft.
- W. fir now 16 ins. diam. brs. S69°24'W, 15.2 ft.; record 15.7 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 14 ins. dia. Brs. N42½°E, 3.8 ft.
- W. fir 9 ins. diam. brs. S29°E, 28.7 ft.

Corner lies approx. 800 ft. east of bend in gravel road along blazed line.

April 7, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 77

V. – 15°