

FIRST RE-ESTABLISHMENT

GCDB 300200

Section corner common to Section 28, 29, 32 and 33, Township 34 South, Range 2 East, W.M.
V = 19°

From the following evidence at the location described below, I set a 1x36-inch G.I. pipe 26 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1976	
T34S R2E	
S 29	28

S 32	33

Original BTs recorded by N. Ford in 1855, found as follows:

- The base of a down and rotted Pine, now 9-inch diameter, containing scribed (backwards) "S" in exposed upper face, bears record S50°W, 52.8 feet.
- A rotted Pine stump, now about 15-inch diameter bears record N70°W, 49.5 feet to estimated lower face.

A clump of alder found at record location of original N.E. BT and take measurements to center of trees at lower blaze:

- Douglas Fir, 15-inch diameter, bears S26°E, 71.05 feet.
- Black Oak, 10-inch diameter, bears S27°W, 56.05 feet.
- Douglas Fir, 6-inch diameter, bears N76½°W, 52.26 feet.

Corner lies at high water mark on the West bank of Butte Cr., about 80 feet South of center of same creek.

- The East creek bank, a vertical rock precipice, about 30 feet high, bears East approximately 85 feet.
- The visible portion of metal bridge bears N24°W.

January 28, 1976
Ed Graham
R. Frost

Approved by: Edward McGinty
County Surveyor