

FIRST RE-ESTABLISHMENT

GCDB 340100

Quarter corner common to Section 33, Township 34 South, Range 2 East and Section 4, Township 35 South, Range 2 East, W.M. $V = 18^\circ$

Set 1x36-inch G.I. pipe 30 ins. in the ground with 2½-inch bronze disc marked:

Jackson County 1976
T34S R2E
33
¼S —
4
T35S

From which:

- An original BT recorded by N. Ford in 1855, now a hollow Black Oak snag, 24-inch diameter, with evidence of old axe work bears record, N66°E, 15.18 feet to estimated lower face.
- The original S.W. BT reported gone in 1955 (E. Smith, surveyor, Medco Co.).

I mound stones around corner, marked new trees C.S. BT and take measurements to center of trees at lower blaze:

- Douglas Fir, 11-inch diameter, bears S5°E, 45.35 feet.
- Douglas Fir, 12-inch diameter, bears N62°W, 17.27 feet.

May 4, 1976

B. Malotte

R. Frost

Witness: A. Rambo, Medco Corp.

K. Bradshaw, Medco Corp.

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 340100

Quarter corner common to Section 33, Township 34 South, and Section 4, Township 35 South, Range 2 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on First Re-establishment in 1976, marked:

JACKSON COUNTY 1976

T34S R2E

S3

¼S —

4

T35S

Bearing trees recorded on said 1st Re-establishment, found with healed double blazes and measured to center at lower blaze.

- D. Fir high-stump, now tipped northerly, brs. record; S5°E, 45.4 ft. to center of root hole.
- D. Fir, now 17 ins. diam. brs. record; N62°W 17.3 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- D. Fir 5 ins. diam. brs. N28½°E, 11.3 ft.
- D. Fir 8 ins. diam. brs. S17°E, 21.2 ft.
- W. Fir 11 ins. diam. brs. S32½°W, 24.4 ft.

Corner lies approx. 650 ft. north of old logging road.

October 20, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 64
V. – 12°45'