

FIRST RE-ESTABLISHMENT

GCDB 340200

Quarter corner Section 28 & 33. Township 34 South, Range 2 East.

Found the witness tree in Section 33 intact, a 24" Fir S.33°E., 33 links and the stump hole of the witness tree in Section 28.

Set a laurel post in correct position from which

- A 24" Fir bears N. 32°W., 48.5 feet.

February 21, 1914
A. T. Brown,
Deputy County Surveyor

H. Ling, Chainman
P. Murphy, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 340200

Quarter corner common to Sections 28 and 33 of Township 34 South, Range 2 East, W.M.

Found at corner position exposed 4 inches, the 2½-inch diameter galvanized iron pipe with a 3½-inch diameter brass cap set by the BLM in 1968 and marked:

T34S R2E
S28
¼S —
S33
1968

Bearing tree recorded on First Re-establishment in 1914 found with healed double blazes and measured to center at lower blaze, a fir snag bears record N22°W, 48.8 feet.

Bearing trees recorded by the BLM in 1968 found with healed single blazes and measured to center at base:

- Douglas Fir now 19-inch diameter bears Record: N14°E, 29.4 feet.
- Cedar now 12-inch diameter bears S34½°W, 5.6 feet. Record S28½°W.

Mark new bearing trees "CS" "BT" and measured to center at lower blaze:

- Cedar 13-inch diameter bears S76½°E, 23.0 feet.
- Douglas Fir 12-inch diameter bears N48°W, 32.0 feet.

Corner lies approximately 250 feet south of gravel logging road.

April 7, 2008

B. Beeman

H. Durkee

Roger R Roberts

Jackson County Surveyor

P - 65

V - 17°10'