

## FIRST RE-ESTABLISHMENT

GCDB 400300

Section corner common to Sections 21, 22, 27 and 28, Township 34 South, Range 2 East, W.M.

Found at the corner position, exposed 9 ins. in a mound of stones with an aluminum post 0.8 ft. south, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T34S R2E	
S21	S22
— —	
S28	S27
1966	

Original bearing tree recorded by Nathaniel Ford of the GLO in 1855, a rotted Fir stob, brs. record; N 48° W, 32.3 ft. to center at base.

Bearing trees recorded by Eugene Henry of the GLO in 1908 found and measured to center at base:

- Cedar, now 29 ins. diam. with a partially healed weathered face, brs. record; N19½°W, 40.8 ft.
- Rotted Fir stump brs. record; S19°E, 21.1 ft.

Bearing trees recorded by the BLM in 1966, found with healed single blazes and measured to center at base:

- W. Fir, blown down, brs. record; N53°E, 50.8 ft. to center of root hole.
- Cedar, now 12 ins. diam. brs. S74°E, 7.3 ft. Record; 7.6 ft.
- Cedar, now 17 ins. diam. brs. S42½°W, 25.7 ft. record; S43½°W.
- W. Fir, blown down, brs. record; N16°W, 44.2 ft. to center of root hole.

Bearing tree of unknown origin:

- A D. Fir 10 ins. with a partially healed single blaze with scribe marks "T34S R2E S21 BT" brs. N37½°W, 18.1 ft. to center at base.

Corner lies southwesterly approx. 80 ft. from dirt logging road.

April 18, 2011

H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 60

V. – 16°25'