

FIRST RE-ESTABLISHMENT

GCDB 400600

Section Corner common to Sections 4 and 9 on the West boundary of Section 3, Township 34 South Range 2 East, W.M.

Found 5/8-inch diameter rebar with 1-inch diameter aluminum cap marked:

RS 461
4 |
— 3
9

Protruding 1 inch above ground surface.

Remove cap and set a 1x 36-inch Galvanized iron pipe over found rebar with a 2½-inch diameter press fit brass cap marked;

JACKSON COUNTY 1998
T34S R2E
4 |
— 3
9

Protruding 4 inches above ground surface.

From which:

- Bearing trees marked on Survey No. 3022, dated 1966, found and measured to the center of tree at base.
- Douglas Fir stump 26-inch diameter and 5 feet high, with healed double blaze, bears N44°W, 15.82 feet, Record N45°W, 16.5 feet.
- Douglas Fir stump 21-inch diameter, with healed double blaze, bears S41°W, 19.65 feet. Record distance 19.1 feet.

Mark new tree 'CS BT and measure to the center of tree at base.

- White Fir 8-inch diameter bears N84¾°W, 29.40 feet.

Corner lies at the East edge of old clear-cut and approximately 240 feet South of dirt road.

January 8, 1998

S. Beecher

T. Newcomb

Roger Roberts

County Surveyor

V = 17½°

P.-2

Search Coordinates: 42°38'08"
122°34'41"