

FIRST RE-ESTABLISHMENT

GCDB 440400

Quarter corner common to Sections 15 and 22 of Township 34 South, Range 2 East, W.M.

Found at corner position, exposed 6 ins., with original stone alongside, and aluminum post with sign 1 ft. south, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1974, and marked:

T34SR2E
S15
¼ —
S22
1974

Bearing trees recorded by the BLM in 1974 found with healed single blazes and measured to center at base;

- Fir snag brs. record; N31°W, 26.4 ft.
- Fir blow down brs record; S71°E, 19.1 ft. to center of stump hole.

Bearing trees by the BLM in 2009 found and measured to center at base;

- Cedar 16 ins. diam. with full scribe brs. N22¼°W, 34.2 ft. as per BLM tag
- P. pine 9 ins. diam. with pitched over face brs. S43¼°W, 28.9 ft as per BLM tag

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- Madrone 17 ins. diam. brs, N73°E, 21.4 ft.
- Madrone 9 ins. diam. brs. S46 ¼°E, 8.3 ft.

Corner lies approx. S25°E, 100 ft. from end of spur road.

April 20, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 91

V. – 11°