

## FIRST RE-ESTABLISHMENT

GCDB 500400

Section corner common to Sections 14, 15, 22 and 23, Township 34 South, Range 2 East, W.M.

Found at the corner position, exposed 4 ins., the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1974, marked:

T34S R2E  
S15 | S14  
—+—  
S22 | S23  
1974

Original bearing trees, recorded by Eugene B. Henry of the GLO in 1908, found high-stumped with healed blazes and measured to center of trees at base:

- D. fir 25 ins. diam. brs. record; N79°E, 19.8 ft.
- W. fir 32 ins. diam. brs. S49°E, 13.7 ft. record; 13.2 ft.
- W. fir 9 ins. diam. brs. S45½°W, 14.0 ft. Record; S44°W, 14.5 ft.
- D. fir 27 ins. diam. brs. N5½°W, 7.9 ft. Record; N11°W.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. fir 12 ins. diam. brs. S58°W, 20.5 ft.
- W. fir 5 ins. diam. brs. S46¼E, 11.5 ft.
- W. fir 5 ins. diam. brs. N26°E, 21.7 ft.
- W. fir 10 ins. diam. brs. N36°W, 50.0 ft.

Corner lies approx. 150 ft. easterly of bend in gravel road.

June 17, 2008

H. Durkee

B. Beeman

Roger R. Roberts

Jackson County Surveyor

P. – 118

V. – 15°40'