

FIRST RE-ESTABLISHMENT

GCDB 540600

Quarter corner common to Sections 2 and 11, Township 34 South, Range 2 East, W.M.

Found at the corner position, exposed 2 ins. in a mound of stones with the original stone alongside, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1968, marked:

T34S R2E
S2
¼—
S11
1968

Single remaining original bearing tree recorded by E. B. Henry of the GLO in 1908:

- A rotted Fir high-stump with a scribed "S" in a chopped-out face, brs. record; N43°E, 16.5 ft. to center at base.

Bearing tree recorded by the BLM in 1968:

- A yew 19 ins. diam. with a healed single blaze, brs. S84°W, 41.6 ft. to center at base. Record; S85°W.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 10 ins. diam. brs. N74½°E, 2.2 ft.
- Cedar 7 ins. diam. brs. N12½°W, 17.5 ft.
- Cedar 8 ins. diam. brs. S40½°E, 20.4 ft.

Corner lies approx. 400 ft. east of logging road.

January 4, 2012

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 108
V. – 16°30'