

FIRST RE-ESTABLISHMENT

GCDB 600100

Section corner on the Township line to Sections 35 and 36, Township 34 South, Range 2 East, and Sections 1 and 2, Township 35 South, Range 2 East.

Found the Southwest BT with the BT scribe intact. Also the Southeast BT down with BT scribe legible and stump hole of the Northwest BT.

From which evidence:

- Set a 2"x 36" galvanized iron pipe 36" in the ground for corner from a 11" Douglas Fir scribed CS-BT bears N. 7°W., 16.3 feet;
- Scribe a 12" Cedar CS-BT which bears N.50½°W., 68.8 feet;
- Scribe a 4" White Fir CS-BT which bears S.46°W., 25.7 feet;
- Scribe an 18" Douglas Fir CS-BT which bears S.59½°E., 29.0 feet.

Note: two BTs in the Northwest quadrant)

July 29, 1955
C. Z. Boyden
E. W. Smith