

FIRST RE-ESTABLISHMENT

GCDB 600540

Quarter corner common to Sections 11 and 12, Township 34 South, Range 2 East, W.M.

Found at the corner position, exposed 1 in. with a steel fence post and sign 0.4 ft. north, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1968, marked:

T34S R2E
¼
S11 | S12
1968

Bearing tree recorded by the BLM in 1968:

- A rotted Fir high-stump with a healed single blaze, brs. record; S61½°E, 19.8 ft. to center at base.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Cedar 7 ins. diam. brs. S47¼°E, 15.2 ft.
- Cedar 13 ins. diam. brs. S1¼°W, 19.1 ft.
- D. Fir 10 ins. diam. brs. N10¾°E, 24.2 ft.

Corner lies approx. 35 ft. north of gravel logging road.

December 13, 2011

H. Durkee

Kerry K. Bradshaw
Jackson County Surveyor

P. – 97
V. – 15°45'