

FIRST RE-ESTABLISHMENT

GCDB 640100

Quarter corner on the Township line to Section 36, Township 34 South, Range 2 East, and Section 1, Township 35 South, Range 2 East.

Found the Southwest BT with scribe from which

- Set a 1"x 36" galvanized iron pipe 34" in the ground for corner.

From which:

- The original BT now a 36" White Fir which bears S.25°W., 17.16 feet;
- Scribe a 26" Cedar CS-BT which bears N.70¼°W., 67.6 feet;
- Scribe an 8" White Fir CS-BT which bears S.24½°E., 42.5 feet.

July 29, 1955
C. Z. Boyden
E. W. Smith

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 640100

Quarter corner common to Section 36, Township 34 South, and Section 1, Township 35 South, Range 2 East, W.M.

Found at the corner position, exposed 6 ins., the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1965, marked:

T34S R2E
S36
¼—
S1
T35S
1965

Bearing trees recorded on 1st Re-establishment in 1955, found with healed double blazes and measured to center at base:

- Cedar, now 44 ins. diam. brs. record; N68°W, 68.6 ft.
- W. Fir, now 22 ins. diam. brs. S24½°E, 42.2 ft. Record; S23½°E.

Bearing tree recorded by the BLM in 1965, found and measured to center of root hole:

- Fir, dead down and rotted, brs. record; S66¾°W, 32.7 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Cedar 6 ins. diam. brs. S48°W, 28.7 ft.
- Only small trees in Northeast quadrant.

Corner lies approx. 1400 ft. northwesterly along blocked and faint road, then north approx. 900 ft.

April 12, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 54

V. – 15°