

FIRST RE-ESTABLISHMENT

GCDB 640400

Quarter corner common to Sections 13 and 24, Township 34 South, Range 2 East, W.M.

Found at the corner position, exposed 1 in. in a mound of stones, the 2 ins. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on Survey No. 9201 in 1981, marked:

T34S R2E
S13
¼ —
S24
1981
RPLS 601

Single remaining original bearing tree recorded by E. B. Henry of the GLO in 1908,

- A D. Fir now 58 ins. diam. with a healed blaze, brs. S10°W, 15.2 ft. record; S13°W, to center at base.

Bearing tree recorded by the BLM in 1968,

- A W. Fir now 26 ins. diam. with a healed single blaze, brs. record; N1°E, 16.8 ft. to center at base.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- D. Fir 6 ins. diam. brs. N18°W, 7.3 ft.
- D. Fir 7 ins. diam. brs. S68½°E, 28.3 ft.

Corner lies approx. 300 ft. south of gravel spur road.

December 14, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 98

V. – 14°50'