

FIRST RE-ESTABLISHMENT

ANGLE POINT

GCDB 700433

Angle point common to Section 18 of Township 34 South, Range 3 East and Section 13 of Township 34 South, Range 2 East, W.M.

Found at corner position , exposed 8 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1970 and marked:

T34S
R2E R3E
AP1 S13 | S18
1970

Original bearing trees recorded by Rufus Moore of the GLO in 1883 found and measured to center

- Cedar 40 ins. diam. sawed stump with a partially healed blaze with scribe '1/4 S 18' brs. record S26½°E, 21.9 ft.
- Cedar now 40 ins. diam. with a healed single blaze brs. record S7°W, 34.2 ft.

Bearing tree recorded on Survey# 9201 found and measured to center of stump hole;

- Fir uprooted sawed stump brs. record N66¾°E, 26.6 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- D. fir 18 ins. diam. brs. N17°E, 31.8 ft.
- W. fir 15 ins. diam. brs. S78¾°E, 26.1 ft.
- D. fir 7 ins. diam. brs. N4½°W, 38.4 ft.

Corner lies approx. 500 ft. southerly from gravel logging road.

March 18, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 26

V. – 16°