

FIRST RE-ESTABLISHMENT

GCDB 100100

Southwest corner Section 31, Township 35 South, Range 2 West, W.M.

Set point for corner 72.6 feet West of Township Corner Section 6, Township 36 South, Range 2 West, W.M. This point checks with the West $\frac{1}{4}$ corner and Northwest corner of Section 31 (see maps), from point for above Southwest corner Section 31.

- A $\frac{1}{2}$ " gas pipe bears South 89° West, 19.6 feet.
- A $\frac{1}{2}$ " gas pipe bears North $34\frac{1}{2}^\circ$ East, 41.6 feet.

June 26, 1914

A. T. Brown, Deputy County Surveyor
H. L. Speck, H. Berian, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 36 AND 31 ONLY
GCDB 100100**

South Township Corner, Township 35 South, Range 2 and 3 West, Willamette Meridian.

Found 5" by 8" sandstone 1 foot below the surface of the ground with a ½" pipe alongside.
Lowered stone 26" below surface of the ground

From which:

- A 10" harrow tooth bears South 30 feet.
- A ½" pipe bears South 88° 15' West, 19.5 feet.
- A 5/8" x 20" bolt bears North 55° West, 66.0 feet.
- A 14" anchor post bears South 57° 45' East, 47.6 feet.

June 7, 1927
Boyden, Deputy County Surveyor
Corlies, Chainman

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 36 AND 31 ONLY
GCDB 100100**

Southeast corner Township 35 South, Range 3 West, and S.W. corner Township 35 South, Range 2 West.

Found small stone 30" below the surface of the County Road, also ½" pipe 19.5 feet Westerly, also ½" pipe Northeasterly and harrow tooth (in poor condition) to South.

Set a 6"x 8" x 16" sand stone with cross on top and CS on North face, top of stone 8" below the surface of the County Road for corner

From which:

- A 3" bronze disc B.M. set a concrete stamped "U.S.G.S. and State Survey, Elev. 1213.4" bears N44¾°W 33.32 feet;
- A ½"x18" iron pipe bears N. 45° E. 42.45 feet (5 feet North of anchor post);
- A 1¼"x 1¾" x ? iron pin bears S52½°E 49.3 feet;
- The center of a cairn of stone 4' x 4' x 5" bears S3½°W73.7 feet;
- The center of a 6" cedar tree bears N14¾°W 167.0 feet;
- The N.W. corner of Township 36 South, Range 2 West and the Northeast corner of Township 36 South, Range 3 West, bears East 72.8 feet.

January 31, 1949
C. Z. Boyden
L. D. Pinkham
G. L. Ray


SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

**FOURTH RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 36 AND 31 ONLY
GCDB 100100**

Township corner common to Sections 36, Township 35 South, Range 3 West, and Section 31, Township 35 South, Range 2 West, W.M. ONLY $V=20^\circ$

Found, 3 feet below the surface of the road, sandstone marked with "X" on top. This has been the recorded location of subject corner since 1914. Reference: First Re-establishment, page 3, Township 35 South, Range 2 West,

Directly over said "X", I set a 2½ x 30 ins. G.I. pipe, with attached 2½ ins. diam. brass cap marked:



5 ins. below asphalt road surface.

The only remaining references recovered, noted on Third Re-establishment, page 17, Township 35 South, Range 2 West, in 1945 found:

- The (brass cap) township corner common to the Northeast corner of Township 36 South, Range 3 West and Northwest corner of Township 36 South, Range 2 West, brs. East (basis of bearing) 72.77 feet. Record: East 72.8 feet.
- Cedar, 16 ins. diam. brs. N14°40'W, 167.25 feet. to center of tree. Record: N14¾°W, 167.0 feet.

I set a center punched railroad spike in center of and flush with the surface of highway which brs. S0°08'W, 18.57 feet.

Corner lies about 18.5 feet North of the intersection of Ramsay Canyon Road and Highway 234.

January 28, 1980
J. Swanson
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR FIFTH RE-ESTABLISHMENT

**FIFTH RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 36 AND 31 ONLY
GCDB 100100**

Township corner common to Section 36, Township 35 South, Range 3 West, and Section 31,
Township 35 South, Range 2 West, W.M. ONLY

Found 7 ins. deep, the brass cap set on 4th re-establishment in 1980. Directly over same, set a 2½
ins. diam. brass cap, in concrete, flush with the surface of Ramsey Road, marked:

T35S
36 | 31
R3W R2W
C.S.
T36S
1995

References reported in 1980 found:

- The (1972) Jackson County brass cap, marking the corner of T36S R2 & 3W, found 12 ins. deep, brs. S89°56'25"E, 72.75 feet. Record: East, 72.77 feet.
- The cedar reported in 1980, was not re-measured.

Take new references:

- A 5/8 x 24 ins. rebar, with Jackson County metal cap, set flush 2 feet South of stop sign, brs. N48°55'33"W, 34.60 feet.
- A 5/8 x 24 ins. rebar, set 1 inch deep in concrete, with Jackson County metal cap marked "ECC" brs. S0°06'22"E, 36.80 feet **Note:** rebar appears to lean northeasterly.
- The (1989) Jackson County brass cap marking the one quarter (special) corner to Sections 36 and 31, brs. N0°06'22"W, 2644.36 feet

Basis of Bearing: Solar Observation

Reference: Project File 95-7

May 25, 1995
R. Frost, Tech.
T. Newcomb, Tech.

Roger Roberts
County Surveyor

V = 20°
P.-48