

PROPORTIONED CORNER

GCDB 200100

Southwest corner Section 32, Township 35 South, Range 2 West, W.M.

This corner established by proportional measurements, from the $\frac{1}{4}$ corners East and West and checks to old fence intersections. Drove a $\frac{1}{2}$ " gas pipe for corner

From which:

- A $\frac{1}{2}$ " gas pipe bears S1°E, 25.0 feet.

July 25, 1914
A. T. Brown, Deputy County Sur
H.L. Speck, H. Berian, CHAINMEN

NOTE: Re-proportioned on Survey No. 3955 in 1969.

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

SPECIAL CORNER

FIRST RE-ESTABLISHMENT

GCDB 200100

Section corner common to Sections 5 and 6, Township 36 South, Range 2 West and Sections 31 and 32, Township 35 South, Range 2 West, W.M.

Found 1 ins. deep, the 5/8 x 30 ins. smooth iron pin set for subject corner on Survey No. 3955, dated 1969.

Replace found pin with a 1 x 36 ins. galvanized iron pipe, set 5 ins. deep, with a 2 1/2 ins. diam. brass cap marked:

T35S R2W	
31	32

6	5
T36S	
C.S.	
1989	

Monuments set and recorded on the above noted survey found:

- 5/8 ins. diam. smooth iron pin, projecting 3 ins. brs. N0°50'W, 25.00 feet.
- 5/8 ins. diam. smooth iron pin, found 4 ins. deep, brs. N67°17'E, 64.69 feet.
- A found 5/8 ins. diam. rebar (leaning Northerly) projecting 4 ins. of unknown origin, brs. N0°26'W, 23.31 feet.

To perpetuate this location, set 5/8 x 24 ins. diam. rebars flush with yellow plastic caps marked: "Jackson C.S.":

- N52°50'W, 38.32 feet.
- S2°51'E, 52.63 feet.

The (brass cap) 1/4 corner, common to Sections 32 and 5, brs. S89°57'10"W, 2650.99 feet.

Corner lies about 15 feet North of the middle of Highway 234 and 20 feet N42°E of the intersection of Highway and private road (c. North) to residence No. 9444.

March 21, 1989
R. Frost, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

P.-74