

FIRST RE-ESTABLISHMENT

GCDB 240100

Quarter section corner on South line Section 32, Township 35 South, Range 2 West, W.M.

Found stone at this point from which I found remains of stump in Section 32 corresponding to the field notes.

- Marked a 16" white oak which bears S. $29\frac{1}{2}^{\circ}$ W., 79.7 feet.

July 25, 1914

A. T. Brown, Deputy County Surveyor

H.L. Speck, H. Berian, Chainmen

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 240100

Quarter corner of the Section Cor. on Twp. line of Section 32 Twp. 35 S., R. 2 W., and Section 5 Twp. 36 S., R. 2 W.

Found pointed stone set for corner also White Oak BT S. $29\frac{3}{4}^{\circ}$ West 79.6 feet as reported by Deputy County Surveyor A.T. Brown July 25, 1914.

Scribe a 26" White Oak C.S.-BT which bears S. $58\frac{3}{4}^{\circ}$ E. 312.1 feet.

Set a $\frac{3}{4}$ " x 21" iron pin which bears South 28.0 feet.

November 12, 1946
C. Z. Boyden
L. D. Pinkham
L. J. Shorey

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 240100

Quarter corner common to Section 32, T35S, R2W and Section 5, T36S, R2W.

Found the pointed stone corner monument 19" below the road surface as found for corner by Deputy County Surveyor, A.T. Brown on the First Re-establishment July 25, 1914.

Set a 1" x 36" galvanized iron pipe with a 2½" bronze cap flush with the road surface and directly over said stone, said cap marked:

T. 35-36S. R.2W.
¼ 32 Cor.
—
5
C.S.
1969

From which:

- The bearing tree reported on said First Re-establishment (now a blaze 24" White Oak stump 7 feet high) Bears S29¾° W, 79.8 feet to the face of the upper blaze;
- The bearing tree reported on the Second Re-establishment by Deputy County Surveyor C. Z. Boyden on November 12, 1946 (now a 26" White Oak with healed blazes bears S58¾° E, 312.0 feet to the face of the lower blaze;
- Found a ⅝" iron pin with O.S.H.D. R/W post alongside which bears N39¼° E, 31.35 feet.

February 6, 1969
F. Roberts, Deputy County Surveyor
Gary Kaiser

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 240100

Quarter corner to Section 32, Twp. 35 South, Range 2 West, and Section 5, Twp. 36 South, Range 2 West, W.M.

Found brass cap, 1 ins. below the asphalt road surface, set on third re-establishment (page 31) in 1969.

References noted on third re-establishment found as follows:

- A 24 ins. diam. white oak stump, 7 feet high, brs. Record: S29°45'W, 79.8 feet to face of upper blaze.
- A $\frac{5}{8}$ ins. diam. iron pin, found flush with the ground, alongside a right of way post, brs. Record: N39°15'E, 31.35 feet.
- A white oak, 28 ins. diam., with healed blazes, bears Record: S58°45'E. No measurement taken.

I set a $\frac{3}{4}$ x 24 ins. smooth iron pin (flush with the ground) which brs. S39°15'W, 31.67 feet.

IN MON CASE

January 23, 1979

B. Malotte

R. Frost

Approved by: Edward McGinty

County Surveyor

SEE NEXT PAGE FOR FIFTH RE-ESTABLISHMENT

FIFTH RE-ESTABLISHMENT

GCDB 240100

Quarter corner to Section 32, Township 35 South, Range 2 West, and Section 5, Township 36 South, Range 2 West, W.M.

Found 2½ ins. diam. brass cap set on the Third Re-establishment, dated 1969, in monument case with no lid. Remove found monument and case and set a 2½ ins. diameter brass cap on a 1½ x 18 ins. galvanized iron pipe in concrete in a new monument case. Cap marked:

T35-36S R2W

32

¼—●—

5

2016

References per the Fourth Re-establishment, dated 1979, found:

- White Oak, 33 ins. diam., standing dead possible lightning strike, with healed blazes and Jackson County Surveyor bearing tree tag bears 1968 record S58°45'00"E, 312.0 feet to estimated lower face. Re-measure 312.87 feet to center of tree at base.
- 5/8" diam. iron pin, found southerly of an East- West bearing wire fence, bears N39°12'52"E, 31.35 feet. Record bearing N39°15'E.
- 3/4" diam. smooth pin 2" deep, located on the southerly side of Tresham Ln. and 20 ft. west of power pole B-29618, bears S39°11'51"W 31.66 feet. Record S39°15'W, 31.67 feet.

Set new reference:

- 5/8" x 24ins. rebar with 1½ ins. diam. aluminum cap marked "Jackson County Surveyor" flush with ground, located on the northerly side of Tresham Ln. 18 Ft. west of a North-South bearing ditch, bears. N24°33'20"W, 49.75 feet.

Corner falls 2 feet south of the painted center of line of Tresham Ln. and 125 feet east of the intersection of Tresham Ln. and Highway 234.

May 5, 2016

L. Madden

J. Hall

Scott Fein

Jackson County Surveyor