

GCDB 300600

Section corner common to Sections 4, 5, 8 and 9, Township 35 South, Range 2 West.

Found a ¾" x 40" iron pin for the corner and the Southeast, Southwest and Northwest original bearing trees which check the location of said iron pin.

Replaced the pin with a 1" x 36" galvanized iron pipe with 2½" bronze cap set 30" in the ground for corner, said cap stamped:

T35S R2W

Section cor.
5 | 4
—|— c.s.
8 | 9
1965

From which:

- The original bearing tree (now an 18" Black Oak with opened faces) bears South 22° West, 5.3 feet;
- The original bearing tree (now a 12" White Oak with opened upper blaze) bears North 44° West, 17.2 feet;
- The original bearing tree (now a 20" Black Oak with scribe marks found after opening the upper blaze) bears South 34° East, 5.9 feet.

From said pipe corner, I establish the following new witness trees:

- A 16" Black Oak scribed "CS-BT" bears South 16½° East, 32.9 feet to the face of the lower blaze;
- A 12" Fir scribed "CS-BT" bears South 75¾° West, 30.0 feet to the face of the lower blaze;
- A 14" Fir scribed "CS-BT" bears North 23¼° West, 24.3 feet to the face of the upper blaze;
- A 12" White Oak scribed "CS-BT" bears North 65½° East, 59.2 feet to the face of the upper blaze.

December 9, 1965
L. D. Pinkham, Deputy County Surveyor
Lloyd Hart