

## FIRST RE-ESTABLISHMENT

GCDB 440100

Re-establishment Quarter section corner on Township line between Section 34, Township 35 South, Range 2 West, and Section 3, Township 36 South, Range 2 West.

Found both original BTs dead with scribe legible in BT to the Northwest from which evidence set a temporary monument to be replaced by Army Engineers.

- A 6" White Oak scribed CS-BT bears S.34°E. 42.3 feet;
- A 7" White Oak scribed CS-BT bears N.51½°W. 62.4 feet.

May 21, 1942  
C. Z. Boyden  
W. R. Young  
L. Withers

This corner now marked with a 6" x 6" x ? concrete monument with 3½" bronze disc.

June 4, 1945  
C. Z. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 440100

One-Quarter corner common to Section 34, Township 35 South, Range 2 West, and Section 3, Township 36 South, Range 2 West, W.M.  $V = 20^\circ$

Found, projecting 5 ins. 6 x 6 ins. concrete pedestal with 3½ ins. brass cap marked:

"U.S. ENGINEERS DEPARTMENT BOUNDARY MONUMENT"

I stamp additional marks:

T35S R2W  
34  
—  
3  
T36S  
CS 1979

Both original BTs are now gone.

Bearing trees marked on first re-establishment, page 16, in 1942, found as follows:

- The stump hole of a down White Oak, 7 ins. diam., scribed "CS" and "BT" in exposed faces, brs. Record: S34°E, 42.3 feet.
- The stump hole of a down and rotted White Oak, 10 ins. diam. with portion alongside containing reverse impression of scribe marks brs. N54½°W, 62.4 feet. Record: N51½°W, 62.4 feet.

**Note:** Addendum to first re-establishment notes found brass cap in concrete set in 1945.

I mk. the new trees:

- A multiple branch (4) Black Oak, 12 ins. diam. at base, I mk. (only) the lower blaze, "CS" which brs. N79°E, 14.42 feet to center of tree, at said blaze.
- White Oak, 7 ins. diam., scribed "CS" and "BT" brs. S50°E, 49.00 feet to center of tree at lower blaze.

June 20, 1979

J. Swanson  
R. Frost

Approved by: Edward McGinty  
County Surveyor