

FIRST RE-ESTABLISHMENT

GCDB 440540

Center-quarter Corner of Section 10, Township 35 South, Range 2 West, W.M.

Found 1 in. diam pipe with 2½ ins. o.d. pot metal filled reducer marked:

RS787
C¼
•
S10

2 ins deep, set on Filed Survey 4149, dated 1969.

From which references taken in 1969 found;

- Southwest corner of a concrete box culvert abutment brs. S36°00'00"W, 17.37 ft. horizontal dist., 17.80 ft. slope dist. Record S36°W, 17.9 ft.
- Northwest corner of the same concrete box culvert abutment brs. N70°06'57"W, 10.62 ft horizontal dist., 11.20 ft. slope dist. Record N72½°W, 11.2 ft.

Set new references, 5/8 x 24 ins. rebar with aluminum caps marked,

JACKSON COUNTY SURVEYOR



Flush with ground;

- Located on the West side of Meadows Rd. 6.6 ft. West of edge of pavement on the extended centerline of Sweet Ln., brs. N01°35'04"W, 52.89 ft.
- Located on the East side of Meadows Rd. 5 ft. East of the edge of pavement and approx. 75 ft. South of the center of Sweet Lane brs. S54°48'55"E, 40.75 ft.

Corner is located in the gravel of the West shoulder of Meadows Rd.

August 7, 2013
S. Beecher
O. Ribanszky

Scott D. Fein
Jackson County Surveyor

P. 18-19