

## PROPORTIONED CORNER - NO FIRST RE-ESTABLISHMENT

GCDB 640100

Quarter Corner on the Township line between Section 1, Township 36 South, Range 2 West and Section 36, Township 35 South, Range 2 West.

Found no evidence of the original bearing trees.

Established the point for corner midway and on line between the Northwest and Northeast corners of said Section 1, which point is now a 6" x 6" x ? concrete monument with the standard U.S. Engineers boundary monument bronze disk,

From which corner monument:

- A 6" White Oak, scribed "CS-BT" bears N75° W, 40.0 feet;
- A 16" White Oak, scribed "CS-BT" bears S52¼°E, 457.45 feet.

May 9, 1942  
C. Z. Boyden  
W. R. Young  
L. Withers

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SPECIAL CORNER

### SECOND RE-ESTABLISHMENT

GCDB 640100

Quarter corner common to Section 36, Township 35 South, Range 2 West and Section 1, Township 36 South, Range 2 West, W.M.

Found projecting 4 ins., the 6x6 ins. concrete monument with 3½ ins. diam. standard U.S. Engineers Department brass cap marked with center punch hole only, reported as the proportionate position for the corner on first re-establishment (T36S), dated 1942\*.

- No evidence of original bearing trees found.

Bearing trees marked in 1942 found:

- White Oak, 16 ins. diam., with healed blazes, brs. N75°W, 40.2 feet to center of tree at lower blaze.
- White Oak bearing tree recorded to be 457.45 feet brs. Record: S52°15'E. Distance not re-measured.

To perpetuate this position set:

- A 5/8 ins. diam. by 24 ins. rebar flush with yellow plastic cap stamped "Jackson C.S." 3 feet North of Power Pole #Copco B16795, brs. S54°31'W, 94.99 feet.
- A 5/8 ins. diam. by 24 ins. rebar flush with yellow plastic cap stamped "Jackson C.S." 3 feet East of center of white oak 18 ins. in diameter, brs. N29°58'W, 63.03 feet.

Corner lies about 30 feet North of middle of East-West road and 0.5 feet South of East-West fence line.

December 6, 1988  
H. Durkee, Tech.  
R. Frost, Tech.

Edward A. McGinty  
County Surveyor

P. - 394

\*NOTE: First re-establishment refers to establishment of Proportioned Corner in 1942. (5/11/2016)