

FIRST RE-ESTABLISHMENT

GCDB 700340

Quarter corner common to Section 19, Township 35 South, Range 1 West and Section 24, Township 35 South, Range 2 West, W.M.

At the corner, found $\frac{3}{4}$ ins. iron pipe projecting 10 ins. high in mound of stone 8 ins. high with 24 ins. base (probable origin 1929 C. Z. Boyden, Deputy County Surveyor), shown on Surveyor No. 3679 by C. Hurst. Directly over said pipe, set a $2\frac{1}{2}$ ins. diam. brass cap marked:

T35S
¼S
R2W R1W
24 | 19
C.S.
1983

From which:

- Remains of an original bearing tree being a deteriorated center stob of a White Oak, brs. N70°52'W, 295.5 feet. Record: N71°W, 294.36 feet.

Take new references:

- A Found $\frac{5}{8}$ ins. iron pin with plastic cap marked K. Weaver, brs. N0°02'50"W, 776.44 feet.
- A found $\frac{1}{2}$ ins. iron pipe, 4 ins. high, brs. N89°59'E, 340.19 feet.

Set a $\frac{5}{8}$ ins. iron pin, with plastic cap marked JACKSON CS, which brs. N89°59'E, 38.24 feet.

- A Pine tree, 29 ins. diam. brs. S8°29'W, 313.3 feet. Marked "CS" "BT".

Corner lies in flat covered area with scattered Chaparral.

September 13, 1983
E. McGinty
R. Templin

Edward McGinty
County Surveyor

P.104-105

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 700340

Quarter corner common to Section 19, Township 35 South, Range 1 West and Section 24, Township 35 South, Range 2 West, W.M.

The corner monument reported on first re-establishment, page 63, dated 1983 is now gone. It, along with the Northeast (iron pin) reference, have apparently been removed by vandals. In the middle of ring of stones, find wood hub and tack, set by D. McMahan (ORLS 1913), reportedly from private references.

Replace said hub and tack with a 1 x 12 ins. galvanized iron pipe set in concrete, flush with the ground surface, in ring of stones, with 2½ ins. diam. brass cap marked:

T35S
R2W R1W
¼S
24 | 19
C.S.
1987

- A bearing tree marked in 1983, a ponderosa pine, now 29 ins. diam., with partly healed pitched-over faces, brs. Record: S8°29'W, 313.3 feet to center of tree at base.
- The visible hole, from the above noted (removed) iron pin reference brs. Record: N89°59'E, 38.24 feet.
- At record location of the original Northwest bearing tree, an 18 ins. diam., tipped out, rotted oak stob, containing evidence of old axe work, is found

Set new references; 5/8 x 24 ins. rebars with yellow plastic caps marked "Jackson C.S." br:

- East, 26.75 feet, 3 ins. deep.
- West, 14.24 feet, flush.

Corner lies in brush field, an estimated 900 feet South of Highway 234.

November 22, 1987
R. Frost, Tech.
S. Beecher, Tech.

Edward McGinty
County Surveyor

V = 17°

P. - 422