

PROPORTIONED CORNER – NO FIRST RE-ESTABLISHMENT

GCDB 700440

Quarter corner on Range line - Section 13, Township 35 South, Range 2 West & Section 18,
Township 35 South, Range 1 West

No evidence of the original corner.

Set a 1" x 36" galvanized iron pipe 24" in the ground on single proportion distance midway
between the section corner to north and south.

- Set a $\frac{3}{4}$ " x 31" iron pin which bears East 40.0 feet.
- Set a $\frac{5}{8}$ " x 24" iron pin which bears West 40.0 feet.

December 8, 1944

C. Z. Boyden

B. L. Campbell

R. E. Welch

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 700440

Quarter corner common to Section 18, Township 35 South, Range 1 West and Section 13, Township 35 South, Range 2 West, W.M.

Found in the middle of and 10 ins. below the asphalt surface of Beagel Road, the 1 ins. diam. galvanized iron pipe, set on first re-establishment*, Township 35 South, Range 2 West, in 1944 by proportionate method.

To perpetuate this position, directly over said pipe, flush with the road surface, set brass cap in concrete mkd:

T35S
R2W R1W
13 | 18
¼ S
C.S.
1981

References recorded in 1944 found:

- Iron pin, $\frac{3}{4}$ ins. diam., found 2 ins. deep, brs. N89°52'E, 39.99 feet Record East, 40.0 feet.
- Iron pin, $\frac{5}{8}$ ins. diam., found 1 ins. deep, brs. S89°52'W, 39.99 feet Record West, 40.0 feet.

March 23, 1981
R. Frost
R. Templin

Edward McGinty
County Surveyor

P.-50

***NOTE:** First re-establishment refers to establishment of Proportioned Corner in 1944. (5/11/2016)