

## CORNER ESTABLISHMENT

### GCDB 100320

South 1/16 corner common to Section 19, Township 36 South, Range 1 East and Section 24, Township 36 South, Range 1 West, W.M.

Set a  $\frac{3}{4}$  x 25 ins. galvanized iron pipe for corner,

From which:

- The northeast corner of the concrete foundation (abandoned school house) brs. S66°W, 197.0 feet.
- Set a  $\frac{5}{8}$  x 25 ins. iron pin which brs. S0°02'W, 80.0 feet, said pin being 15 feet north of the center of an irrigation canal.

April 5, 1945  
C. Z. Boyden  
R. E. Welch  
F. Foley  
L. J. Shorey

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

GCDB 100320

South one-sixteenth corner common to Section 24, Township 36 South, Range 1 West and Section 19, Township 36 South, Range 1 East, W.M.

Found, 11 ins. below the asphalt surface of Yankee Creek Road, the ¾-ins. diam. galvanized iron pipe set as recorded in Intermediate Corner book, in 1945.

The ⅝-ins. diam. iron pin reference, set in 1945, is found with bent top, 16 ins. deep, brs. S0°02'E, 80.0 feet to vertical lower section of pin. Record; S0°02'W.

Found rebar, ⅝-ins. diam. flush with the ground, brs. S0°02'E, 40.52 feet.

Scribe cross in the top of concrete curbs of:

- Bridge No. 213, North end of West curb, brs. S2°15'E, 89.19 feet.
- Bridge No. 201, East end of South curb, brs. S71°08'W, 49.31 feet.
- Bridge No. 201, East end of North curb, brs. N74°15'W, 63.96 feet.

January 6, 1980  
R. Frost  
R. Templin

Edward McGinty  
County Surveyor

P.-3

### NOTE:

January 16, 1981, Jackson County Public Works set a spiral brass cap, 2½ ins. diam.:

"T36S"  
R1W, R1E  
24 | 19  
S 1/16  
1981