

## FIRST RE-ESTABLISHMENT

GCDB 100360

North 1/16 corner common to Section 24, Township 36 South, Range 1 West and Section 19, Township 36 South, Range 1 East, W.M.

Set a  $\frac{3}{4}$  x 12 ins. iron pin for corner, from which:

- An 18 ins. White Oak scribed C.S. on new blaze (scribed BT on old blaze) brs. N83 $\frac{1}{4}$ °W, 109.1 feet.
- Scribed a 10 ins. White Oak BT which brs. S45 $\frac{1}{4}$ °E, 40.8 feet.

April 6, 1945

C. Z. Boyden

R. E. Welch

F. Foley

L. J. Shorey

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

### GCDB 100360

North one-sixteenth corner common to Sections 19, Township 36 South, Range 1 East, and Section 24, Township 36 South, Range 1 West, W.M.

In the top of 1 in. diam. G.I. pipe, found 3 ins. below the surface of Meridian Road in concrete, set hub tack in cement. Said pipe was set by Jackson County Public Works Department over the 3/4 in. diam. iron pin recorded as the corner on First re-establishment, Township 36 South, Range 1 East, in 1945.

References set by Public Works Department prior to reconstruction of Meridian Road:

- 5/8 x 25 ins. rebar, found projecting 1 in. brs. S89°58'E, 30.00 feet.
- 5/8 x 18 ins. rebar, found projecting 1 in. brs. N89°58'W, 30.00 feet.

Bearing trees marked on First re-establishment found:

- White Oak, 15 ins. diam., with healed blazes, brs. S45°28'E, 40.85 feet to center of tree at lower blaze. Record; S45¼°E, 40.8 feet.
- White Oak, 26 ins. diam., with healed blazes, brs. N83°08'W, 109.1 feet to estimated face of blaze. Re-measured 109.85 feet to center of tree at lower blaze. Record; N83¼°W, 109.1 feet.

Basis of Bearings: The (brass cap) corner of Sections 13, 18, 19 and 24 brs. N0°02'E, per Survey No. 4467.

August 26, 1980  
R. Frost  
D. Danielsen

Edward McGinty  
County Surveyor

P.-174

**SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT**

**THIRD RE-ESTABLISHMENT  
GCDB 100360**

North one-sixteenth corner common to Sections 19, Township 36 South, Range 1 East, and Section 24, Township 36 South, Range 1 West, W.M.

Found the 1 in. daim. pipe described on the Second Re-establishment, dated 1980, 4 ins. deep.

Set a 2½ ins. diam. brass cap marked;

T36S  
N 1/16 24 | 19  
R1W | R1E  
2010

In cement directly over found pipe and flush with pavement.

From which;

Bearing tree marked by Jackson County in 1945 found;

- White Oak 19 ins. diam. with healed blazes brs. S44°58'E, 40.80 ft. Second Re-establishment record S45°28'E, 40.85 ft.

Second Re-establishment reference found;

- 5/8 diam. iron pin flush with ground located 1 ft. West of North-South fence line brs. N89°58'37"W, 29.98 ft. Record N89°58'W, 30.00 ft.

Set new reference;

- 5/8 in. x 24ins. rebar with 2 ins. diam aluminum cap marked 'JACKSON COUNTY SURVEYOR' flush with ground and located 1.5 ft. east of wood fence post at south end of fence brs. N30°12'43"E, 62.03 ft.

The 2½ ins. diam. brass cap at the Section Corner common to Sections 13,18,19,24 Township 36 South Range 1 West and 1 East brs. N00°02'00"E, 1326.28 ft.

Corner is located in the middle of the southbound lane of Meridian Rd.

August 4, 2010

S. Beecher

S. Fein

Kerry K. Bradshaw

County Surveyor

P. - 42

Series II, Book I