

PROPORTIONED CORNER

GCDB 100540

Quarter Corner on Willamette Meridian, Section 12, Township 36 South, Range 1 West, and Section 7, Township 36 South, Range 1 East, W.M.

Set a 1" x 36" iron pipe 6" below the surface of the ground for corner on single proportion distance, from which;

- A ½" x 22" iron pin bears East 30.0 feet.
- Set a ½" x 24" iron pin which bears West, 30.0 feet.

April 7, 1945
C. Z. Boyden
L. J. Shorey
F. Foley

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

SPECIAL CORNER

FIRST RE-ESTABLISHMENT

GCDB 100540

Quarter corner common to Section 12, Township 36 South, Range 1 West and Section 7, Township 36 South, Range 1 East, W.M.

Found 5/8-ins. smooth iron pin on East and West side of road, set in 1945, page 20. From this evidence set a 1 x 16 ins. galvanized iron pipe flush with pavement of Meridian Road, with a 2 1/2 ins. diam. brass cap marked:

T36S
1/4S
R1W 12 | 7 R1E
C.S.
1990

Found 5/8-ins. pins:

- 5 ins. deep, brs. East, 30.04 feet. Record; 30.0 feet.
- 6 ins. deep, brs. N89°58'W, 30.04 feet. Record; West, 30.0 feet.

Set new references:

- 5/8 x 24 ins. rebar with yellow plastic caps marked "Jackson CS" flush with ground.
- Brs. S40°36'E, 46.25 feet. Rebar is 2 feet West of North-South fence line.
- Brs. N39°13'W, 36.82 feet. Rebar is 2 feet East of North-South fence line.

Corner lies in the center of the Westerly lane of Meridian Road.

August 22, 1990
T. Newcomb, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

P. -125