

## GCDB 100600

Corner on Willamette Meridian, Section 1 and 12, Township 36 South, Range 1 West, and Section 6 and 7, Township 36 South, Range 1 East, W.M.

Found no evidence of stone set for corner, however, I found a 1" pipe, 6 feet South of corner which was verified by J. B. Rader and W.C. Pool as being the pipe which was set 6 feet South of the original corner; also see McKissick record of the Stevens Road in 1913 at which time Mr. McKissick found the original section corner stone.

Set a 3 x 4 x 14" stone in the center of the county road 6 feet North of the above mentioned 1" pipe for section corner, from which:

- Set a 1" pipe which bears S45°W, 42.42 feet.
- Set iron leaf of buggy spring N45°E, 42.42 feet.

August 26, 1926

C. Z. Boyden, Deputy County Surveyor

J.D. Hight, Chainman

Stanley, Rader, Pool, Aerns, Present

**NOTE:** See later survey on Page 21

**SEE NEXT PAGE FOR ESTABLISHMENT OF PROPORTIONED CORNER**

## PROPORTIONED CORNER – NO FIRST RE-ESTABLISHMENT

GCDB 100600

Section Corner on Willamette Meridian, Sections 1 & 12, Township 36 South, Range 1 West, and Sections 6 & 7 Township 36 South, Range 1 East, W.M.

Set a 2" x 36" iron pipe with top 6" below the surface of the county road for corner on single proportion distance between the first  $\frac{1}{4}$  section corner to the North and the fourth section corner to the South, which corners were established from the original bearing trees.

For references:

- A  $\frac{1}{2}$ " x 18" iron pin which bears West 30.0 feet.
- A 1" x 26" iron pipe which bears S45°02'W, 42.42 feet.
- A  $\frac{3}{8}$ " x 18" iron pin which bears S89°57½'E, 30.0 feet.
- A  $\frac{1}{4}$ " x 1½" x 34" steel spring which bears N45°E, 42.42 feet.

The re-established corner set in 1926 bears N3°27'E, 10.58 feet. Destroyed old re-established corner and references.

The more extensive survey made in 1945 has shown the re-established corner set in 1926 is not consistent with the official government records; therefore the correction.

April 7, 1945  
C. Z. Boyden  
L. J. Shorey  
F. Foley

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 100600

Section corner common to Sections 6 and 7, Township 36 South, Range 1 East, and Sections 1 and 12, Township 36 South, Range 1 West, W.M.

To perpetuate a County Surveyor 1945 proportional position; found a 2 ins. diam. pipe, 30 ins. deep. Directly over said pipe, set a 1 ins. iron pipe, 36 ins. long with a 2½ ins. cap marked:

C.S.  
1983

From which:

C.S. 1945 references:

- Found S steel spring, ¼ x 1½ ins. 27 ins. deep bearing N45°05'E, 42.55 feet. Record; N45°E, 42.42 feet.
- Found a ¾-ins. iron pin leaning westerly, 12 ins. deep bearing S89°57½°E, 29.83 feet. Record; 30.00 feet.
- Found a 1 ins. diam. iron pipe, 8 ins. deep on a north-south fence bearing S44°55'W, 42.22 feet. Record; S45°02'W, 42.42 feet.
- Found a ½ ins. diam. iron pin, 6 ins. deep, on north and south fence bearing west, 30.00 feet.

New references:

- Found ½ ins. rebar protruding 2 ins. (origin unknown), found on survey 8676, bearing N88°21'W, 29.67 feet.
- Easterly pole of power tower, marked 8/48, brs. N61°45'W, 32.6 feet

Corner lies approximately 1.0 feet West of center pavement and 25 feet southerly of drive westerly to residence 2945 Meridian road.

October 31, 1983  
E. McGinty  
R. Frost

Edward McGinty  
County Surveyor


V = 21½°  
P. -142

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT  
GCDB 100600**

Section corner common to Sections 6 and 7, Township 36 South, Range 1 East, and Sections 1 and 12, Township 36 South, Range 1 West, W.M.

Found the 2½ ins. diam. brass cap set on the Second Re-establishment, dated 1983, 1 in. deep in hole in pavement, marked:



References recorded in 1983 found;

- ½ in. iron pin 6 ins. deep bears westerly, severely bent not measured.
- Easterly pole # R 8/48 of a power line tower bears N62°11'14"W, 35.28 ft. to center of pole, 34.69 ft. to face. Record N61E45'W, 32.6 ft.

New references;

- Found Yellow Plastic Cap marked; KAISER RLS803, 4 ins. deep bears S89°48'51"E, 29.94 ft.
- Set new references 5/8 x 24 ins. rebar with aluminum caps mkd;

JACKSON COUNTY  
△  
SURVEYOR

1. 1 in. deep at the East edge of pavement of Meridian Rd. bears S24°05'23"E, 33.65 ft.
2. 1 in. deep at the West edge of pavement of Meridian Rd. bears S25°21'33"W, 24.92 ft.

Corner is located approx. 1 ft. West of the center of pavement in Meridian Rd. driveway to residence 2945 to West and 2996 to East.

April 23, 2012  
S. Beecher

Kerry K. Bradshaw  
County Surveyor

P. - 41