

## FIRST RE-ESTABLISHMENT

GCDB 140100

Quarter Section corner on Township Line - Section 31, Township 36 South, Range 1 East and Section 6, Township 37 South, Range 1 East.

Found mound of stone to mark the corner, also remains of white oak bearing tree to northeast as established by Surveyor Elksnat in 1905; also found remains of pine line tree to east.

Set a 1" x 36" galvanized iron pipe 30" in the ground for corner at the exact location of said mound of stone,

From which:

- A 6" White Oak scribed C.S.-BT bears S.41°E. 60.0 feet.
- Scribed an 8" white oak C.S.-BT which bears N.63°W., 65.1 feet.

May 4, 1945  
R. E. Welch  
F. Foley

C. Z. Boyden  
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 140100

Quarter corner common to Section 31, Township 36 South, Range 1 East, and Section 6, Township 37 South, Range 1 East, W.M.

At the corner, found the 1 ins. diam. galvanized iron pipe, projecting 3 ins., in ring of stone, set on first re-establishment, in 1945.

In the top of said pipe, set a 2½ ins. diam. brass cap marked:

JACKSON COUNTY 1981  
T36S R1E  
31  
¼S —  
6  
T37S

From which bearing trees recorded in 1945 are found as follows:

- White Oak, 8 ins. diam., with healed blazes, brs. S41°E, 60.10 feet to center of tree. Record; 60.0 feet.
- White Oak, (dead top), 9 ins. diam., with healed blazes, brs. Record: N63°W, 65.1 feet to estimated face. Re-measured; 65.43 feet to center of tree.

Mk a new tree "CS" "BT":

- Black Oak, 9 ins. diam., brs. N21°W, 16.00 feet to center of tree at lower blaze.

Corner lies at the corner of North and West bearing fence lines.

February 10, 1981  
R. Frost  
R. Templin

Edward McGinty  
County Surveyor

V = 19½°  
P. -28