

FIRST RE-ESTABLISHMENT

GCDB 200300

Corner to Sections 19, 20, 29, 30, Township 36 South, Range 1 East.

Found 3½" bronze disc set in concrete (marked U.S. Engineers boundary monument) located on lower bank of irrigation canal for corner,

From which:

- The original bearing tree, a 12" white oak with scribe visible, bears S49°W, 52.8 feet as per official government field notes.
- Also found dead oak snag with old axe marks which agrees with said official field notes.
- Chiseled a cross on top of concrete headwall outlet end of Yankee Creek irrigation siphon, said cross being on line with center line of siphon, which cross bears S80½°E, 70.0 feet.
- Scribed an 8" white oak C.S.-BT which bears N43°E, 90.2 feet.
- Scribed a 12" white oak C.S.-BT which bears N35¼°W, 70.2 feet.

March 15, 1945
C. Z. Boyden
R.E. Welch
F. Foley

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 200300

Section corner common to Sections 19, 20, 29 and 30, Township 36 South, Range 1 East, W.M.
V = 20°

Found the 3½ ins. bronze disc as first re-established by C. Z. Boyden, March 15, 1945, in Jackson County Survey Records marked:

U.S. Engineer Department
Portland District
*
Boundary Monument
(Usual penalty for disturbing)

Set in a rough 12 ins. diam. concrete pad, unknown depth, firm, from which:

- The original bearing tree described in first re-establishment, now a 14 ins. diam. White Oak, bears S49°W, 54.0 feet to center of tree at lower blaze. Record; S49°W, 52.8 feet, upper blaze open but no discernible marks.

I scribed "CS-BT":`

- White Oak, 17 ins. diam., brs. S1°E, 55.85 feet to center of tree at top of lower blaze. Tree is located on wire fence line course S17°E-N17°W.
- The Southeast corner of the concrete siphon outlet mouth wall at its intersection with the southeast concrete wing wall brs. N14¼°W, 19.15 feet.
- No close bearing trees in the Northeast quadrant. This corner now lies East 12 feet of the Easterly corner of the end of the siphon wing wall. Land has been cleared and leveled.
- New Siphon was constructed in 1956.

May 2, 1979
J. Swanson

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT
GCDB 200300**

Section corner common to Sections 19, 20, 29 and 30, Township 36 South, Range 1 East, W.M

Found the 3½ ins. diam. brass cap marked;

U.S. ENGINEER DEPARTMENT
PORTLAND DISTRICT



BOUNDARY MONUMENT

Set in concrete post approximately 12 ins. in diam and flush with the ground.

From which;

- Original bearing tree a White Oak 17 ins. diam. brs. Second Re-establishment, dated 1979, record S49°W, 54.0 ft to center of tree at base.

Second Re-establishment bearing tree

- A White Oak 21 ins. diam. brs. record S01°E, 55.85 ft. to center of tree at lower blaze, fencing around tree.
- The southeast inside corner of the intersection of the headwall and wingwall of concrete irrigation siphon brs. record N14°15'W, 19.15 ft.

Set new references: 5/8 x 24 ins. rebar with 2 ins. diam. aluminum caps marked;

JACKSON COUNTY



SURVEYOR

- Protruding 9 ins. above ground on North side of ditch road, brs. N26°45'W, 40.09 ft.
- Protruding 3 ins. above ground, located 3 ft. North of an east-west barbwire fence, brs. S54°11'E, 69.04 ft.

Corner is located West of ditch road and 21 ft. southerly of the center of siphon headwall.

July 25, 2011
S. Beecher

Kerry K. Bradshaw
County Surveyor

P.- 2