

FIRST RE-ESTABLISHMENT

GCDB 200540

Quarter corner common to Sections 7 & 8, Township 36 South, Range 1 East.

Found original BT to Northeast; also original BT stump to Southwest.

A 4' x 6" x ? stone set for (this corner stone was found by C. Z. Boyden and recognized as the true ¼ section corner in 1927) (we now find an iron pin 0.9 East of stone) corner.

Accept stone as true corner which checks course to both original BTs and distance to BT to Southwest:

- The original BT an 18" Black Oak, plainly scribed, bears N.25°E., 25.0 feet.
- Scribe an 18" black oak C.S.-BT which bears S.49½°W., 91.8 feet.

September 21, 1933

P. B. Rynning, County Surveyor

C. Z. Boyden, Deputy County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 200540

Quarter corner common to Sections 7 and 8, Township 36 South, Range 1 East.

Found the 4"x6" stone with cross on top for corner as reported on the first re-establishment by County Surveyor P. B. Rynning on September 21, 1933.

Replaced said stone with a 1" x 36" galvanized iron pipe, 30" in the ground, with a 2½" bronze cap stamped:

T36S R1E
¼ 7 | 8 cor.
C.S.
1969

From which:

- The original bearing tree, now a 26" Black Oak, plainly scribed "¼S", bears N25°E, 25.1 feet to the face of the upper blaze;
- The original bearing tree, now a badly decayed Black Oak stump, bears S49°W, 43.1 feet to the center of said stump.
- The bearing tree marked on said first re-establishment now a 20" sawed Black Oak stump, scribed "BT" bears S49½°W, 91.9 feet to the face of the lower blaze;
- A ½" pipe with 45-90 caliber shell casing in the top (this was reported as a pin on the first re-establishment) bears Easterly, 0.86 feet.

I mark the following new trees:

- An 11" Black Oak, scribed "CS-BT" bears S79¾°W, 71.2 feet to the face of the upper blaze;
- A 6" White Oak, scribed "CS-BT" bears S19°E, 70.8 feet to the face of the lower blaze.

January 29, 1969
F. Roberts, Deputy County Surveyor
Gary Kaiser

NOTE:

Replaced pipe 4/28/75

See corner card. R.F.


SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 200540

Quarter corner common to Sections 7 and 8, Township 36 South, Range 1 East, W.M.

Found at the corner, 1 in. deep, the 2½ ins. diam. brass cap set on second re-establishment in 1969 and marked:



One in. diam. galvanized iron pipe, upon which, said brass cap was set reported destroyed in 1975, and replaced with new 1 x 36 ins. galvanized iron pipe in exact position with same 2½ ins. diam. brass cap cemented in the top.

Trees marked on second re-establishment found and measured to center of tree at lower blaze:

- Black Oak, now 15 ins. diam. with healed blazes, brs. S79¼°W, 71.6 feet. Record: 71.2 feet to face of upper blaze.
- White Oak, now 10 ins. diam. with healed blazes, brs. S19°E, 71.0 feet. Record: 70.8 feet to face of lower blaze.

Three-quarter in. diam. axle, flush, reported as a ½ in. diam. pipe with a 45-90 caliber shell casing on top on second re-establishment, brs. Record: Easterly, 0.86 feet.

Take new references: 5/8 x 24 ins. rebars with 1½ ins. diam. aluminum caps, set flush and marked:



Bears:

- N56¾°E, 17.50 feet.
- S48¼°E, 22.78 feet.

Corner lies on easterly edge of graveled road (driveway) and 16 feet Westerly of north-south board fence. Set steel fence post, with location marker attached, East, 2.0 feet from corner.

January 28, 2002

H. Durkee

T. Newcomb

Roger Roberts

Jackson County Surveyor

P. -9

V. = 17°